


LYCOMING ENGINES
652 OLIVER STREET
WILLIAMSPORT, PA 17701
P +001 570.323.6181
F +001 570.327.7066

Aftermarket Engine Price List



AVAILABLE FROM AUTHORIZED
LYCOMING DISTRIBUTORS

Effective July 5, 2011

(All prices subject to change without notice)

LYCOMING

LYCOMING.COM

© 2010 Avco Corporation. All Rights Reserved.

SALES TERMS AND CONDITIONS

1. All prices are subject to change without notice.
2. All prices are Ex Works Williamsport, PA, U.S.A.
3. Engine availability subject to change without notice.
4. New Exchange or New Outright Engines - New engines may be purchased without an exchange engine core (outright) or on an exchange basis. New Outright list price is calculated by simply multiplying the published new exchange list price by 1.2.
5. Rebuilt Exchange or Rebuilt Outright Engines - Rebuilt engines are normally purchased on an exchange basis. Occasionally, upon request Lycoming Engines may approve the sale of a Rebuilt engine on an outright basis; however, only Lycoming Engines has this authority, prior written authorization is required. Rebuilt Outright list price, when approved is usually the same as the published new exchange list price.
6. Overhauled Exchange Engines - Overhauled engines may only be purchased on an exchange basis.
7. Engine mounting brackets are not furnished on rebuilt and overhauled engines.
8. Orders for rebuilt and overhauled engines are subject to the availability of core engines.
9. Engines sold on an exchange basis are shipped prior to the receipt of the exchange engine core and will be billed a core charge as listed on the applicable engine price list.
10. Exchange engine core prices are NET and are not subject to any discount.
11. All exchange engine cores must comply with Lycoming Engines exchange engine core policy as communicated in the latest edition of Lycoming Service Letter 250 and must be returned to the Lycoming Engines factory accompanied by a completed Factory Return Authorization Worksheet (Form 2500)
12. All engines returned for custom overhaul or custom rebuild must comply with Lycoming Engines exchange engine core policy as communicated in the latest edition of Lycoming Service Letter 250.
13. Bills of lading for exchange engine cores should identify the shipment as "INTERNAL COMBUSTION ENGINE" and the value should be declared "NOT TO EXCEED \$5.00 PER POUND" in order to obtain the lowest freight rate.
14. Lycoming Engines will not be responsible for non-engine accessories returned on the exchange engine core. (Vacuum pumps, fittings, hydraulic pumps, governors, hoses, etc.)
15. Replacement engines for Aerobatic aircraft installation may not include the aerobatic kit, hoses or fittings.
16. Generators are no longer available for those models originally supplied with a generator. If a LYCOMING ENGINES generator was supplied with the original engine, DO NOT RETURN THE GENERATOR WITH THE EXCHANGE ENGINE CORE.
17. Regulators, relays and starter switches are no longer available from Lycoming Engines.

Lycoming Engine Sales Program Comparison

	Lycoming Factory Rebuilt at Overhaul Price Program	Lycoming Loyalty Program
Promotion Benefits:	Purchase Factory Rebuilt Engines at Factory Overhaul prices! Saving up to \$5,000.00	Upfront price discounts of up to \$1,900.00 on a Factory New, Rebuilt or Overhauled engine.
Price Discounts:	Rebuilt Engines discounted to corresponding Overhaul price.	Discounted according to the matrix below. Determined by the type of engine purchased and the heritage of the exchange engine core when it last shipped from the Factory.
Exchange Engine Core Requirements:	Factory New Only. Exchange engine core must be "First Run" and not have been overhauled or rebuilt since shipping from the Factory as a new engine. Exchange engine core must have been placed in service on or after January 1 st , 1990. Exchange engine core must comply with the Lycoming Engines exchange engine core policy as communicated in the latest edition of Lycoming Service Letter 250.	Factory New, Rebuilt or Overhauled. Exchange engine core must not have been field overhauled since it last shipped from the Factory. Exchange engine core must have been placed in service on or after January 1 st , 1990. Exchange engine core must comply with the Lycoming Engines exchange engine core policy as communicated in the latest edition of Lycoming Service Letter 250.
Additional Program Conditions:	Exchange engine core values are listed in the "New Exchange Engine Core Values" table. Program discounts cannot be combined with the Fleet Rebate program	Exchange engine core values are listed in the "Select Exchange Engine Core Values" table. Program discounts cannot be combined with the Fleet Rebate program

Lycoming Factory Loyalty Program Discount Table

		Purchasing		
		New	Rebuilt	Overhaul
CORE CONDITION		4 Cylinder		
	New	\$1,200	N/A	\$1,200
	Rebuilt	\$800	\$800	\$800
	Overhaul	\$600	\$600	\$600
		4 Cylinder Turbo		
	New	\$1,300	N/A	\$1,300
	Rebuilt	\$900	\$900	\$900
	Overhaul	\$800	\$800	\$800
		6 Cylinder		
	New	\$1,800	N/A	\$1,800
	Rebuilt	\$1,200	\$1,200	\$1,200
	Overhaul	\$900	\$900	\$900
	6 Cylinder Turbo			
New	\$1,900	N/A	\$1,900	
Rebuilt	\$1,300	\$1,300	\$1,300	
Overhaul	\$1,000	\$1,000	\$1,000	

New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-AEIO-320-D1B	\$17,560
NC-AEIO-320-D2B	\$17,560
NC-AEIO-320-E1B	\$17,560
NC-AEIO-320-E2B	\$17,560
NC-AEIO-360-A1A	\$18,860
NC-AEIO-360-A1B	\$18,860
NC-AEIO-360-A1B6	\$18,860
NC-AEIO-360-A1D	\$18,860
NC-AEIO-360-A1E	\$18,860
NC-AEIO-360-A2C	\$18,860
NC-AEIO-360-B1B	\$18,860
NC-AEIO-360-B1F	\$18,860
NC-AEIO-360-B1G6	\$18,860
NC-AEIO-360-B1H	\$18,860
NC-AEIO-360-B2F	\$18,860
NC-AEIO-360-B4A	\$18,860
NC-AEIO-360-H1A	\$18,860
NC-AEIO-360-H1B	\$18,860
NC-AEIO-540-D4A5	\$21,870
NC-AEIO-540-D4B5	\$21,870
NC-AEIO-540-D4D5	\$21,870
NC-AEIO-540-L1B5	\$24,170
NC-AEIO-540-L1B5D	\$24,170
NC-HIO-360-A1A	\$18,860
NC-HIO-360-B1A	\$18,860
NC-HIO-360-C1A	\$18,860
NC-HIO-360-C1B	\$18,860
NC-HIO-360-D1A	\$18,860
NC-HIO-360-E1AD	\$18,860
NC-HIO-360-E1BD	\$18,860
NC-HIO-360-F1AD	\$18,860
NC-HIO-360-G1A	\$18,860
NC-HO-360-C1A	\$17,560
NC-IO-320-B1A	\$17,560
NC-IO-320-D1A	\$17,560
NC-IO-320-D1B	\$17,560
NC-IO-320-E1B	\$17,560
NC-IO-320-E2A	\$17,560
NC-IO-320-E2B	\$17,560
NC-IO-360-A1A	\$18,560
NC-IO-360-A1B	\$18,560
NC-IO-360-A1B6	\$18,560
NC-IO-360-A1B6D	\$18,560
NC-IO-360-A1D	\$18,560
NC-IO-360-A1D6	\$18,560
NC-IO-360-A2B	\$18,560
NC-IO-360-A3B6	\$18,560
NC-IO-360-A3B6D	\$18,560

Select Exchange Engine Core	
Part Number	Value
SC-AEIO-320-D1B	\$15,100
SC-AEIO-320-D2B	\$15,100
SC-AEIO-320-E1B	\$15,100
SC-AEIO-320-E2B	\$15,100
SC-AEIO-360-A1A	\$16,400
SC-AEIO-360-A1B	\$16,400
SC-AEIO-360-A1B6	\$16,400
SC-AEIO-360-A1D	\$16,400
SC-AEIO-360-A1E	\$16,400
SC-AEIO-360-A2C	\$16,400
SC-AEIO-360-B1B	\$16,400
SC-AEIO-360-B1F	\$16,400
SC-AEIO-360-B1G6	\$16,400
SC-AEIO-360-B1H	\$16,400
SC-AEIO-360-B2F	\$16,400
SC-AEIO-360-B4A	\$16,400
SC-AEIO-360-H1A	\$16,400
SC-AEIO-360-H1B	\$16,400
SC-AEIO-540-D4A5	\$19,400
SC-AEIO-540-D4B5	\$19,400
SC-AEIO-540-D4D5	\$19,400
SC-AEIO-540-L1B5	\$21,700
SC-AEIO-540-L1B5D	\$21,700
SC-HIO-360-A1A	\$16,400
SC-HIO-360-B1A	\$16,400
SC-HIO-360-C1A	\$16,400
SC-HIO-360-C1B	\$16,400
SC-HIO-360-D1A	\$16,400
SC-HIO-360-E1AD	\$16,400
SC-HIO-360-E1BD	\$16,400
SC-HIO-360-F1AD	\$16,400
SC-HIO-360-G1A	\$16,400
SC-HO-360-C1A	\$15,100
SC-IO-320-B1A	\$15,100
SC-IO-320-D1A	\$15,100
SC-IO-320-D1B	\$15,100
SC-IO-320-E1B	\$15,100
SC-IO-320-E2A	\$15,100
SC-IO-320-E2B	\$15,100
SC-IO-360-A1A	\$16,100
SC-IO-360-A1B	\$16,100
SC-IO-360-A1B6	\$16,100
SC-IO-360-A1B6D	\$16,100
SC-IO-360-A1D	\$16,100
SC-IO-360-A1D6	\$16,100
SC-IO-360-A2B	\$16,100
SC-IO-360-A3B6	\$16,100
SC-IO-360-A3B6D	\$16,100

New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-IO-360-B1B	\$18,560
NC-IO-360-B1E	\$18,560
NC-IO-360-B1F	\$18,560
NC-IO-360-B1G6	\$18,560
NC-IO-360-C1B	\$18,560
NC-IO-360-C1C	\$18,560
NC-IO-360-C1C6	\$18,560
NC-IO-360-C1D6	\$18,560
NC-IO-360-C1E6	\$18,560
NC-IO-360-C1F	\$18,560
NC-IO-360-C1G6	\$18,560
NC-IO-360-L2A	\$18,560
NC-IO-360-M1A	\$18,560
NC-IO-360-M1B	\$18,560
NC-IO-540-AA1A5	\$21,870
NC-IO-540-AA1B5	\$21,870
NC-IO-540-AB1A5	\$21,870
NC-IO-540-AC1A5	\$21,870
NC-IO-540-AE1A5	\$21,870
NC-IO-540-C1B5	\$21,870
NC-IO-540-C4B5	\$21,870
NC-IO-540-C4D5	\$21,870
NC-IO-540-C4D5D	\$21,870
NC-IO-540-D4A5	\$21,870
NC-IO-540-D4B5	\$21,870
NC-IO-540-G1D5	\$21,870
NC-IO-540-J4A5	\$21,870
NC-IO-540-K1A5	\$21,870
NC-IO-540-K1A5D	\$21,870
NC-IO-540-K1B5	\$21,870
NC-IO-540-K1D5	\$21,870
NC-IO-540-K1E5	\$21,870
NC-IO-540-K1F5	\$21,870
NC-IO-540-K1G5	\$21,870
NC-IO-540-K1G5D	\$21,870
NC-IO-540-K1J5	\$21,870
NC-IO-540-K1J5D	\$21,870
NC-IO-540-K1K5	\$21,870
NC-IO-540-L1C5	\$21,870
NC-IO-540-M1A5	\$21,870
NC-IO-540-M1B5D	\$21,870
NC-IO-540-M1C5	\$21,870
NC-IO-540-N1A5	\$21,870
NC-IO-540-R1A5	\$21,870
NC-IO-540-S1A5	\$21,870
NC-IO-540-T4A5D	\$21,870
NC-IO-540-T4B5	\$21,870
NC-IO-540-T4B5D	\$21,870

Select Exchange Engine Core	
Part Number	Value
SC-IO-360-B1B	\$16,100
SC-IO-360-B1E	\$16,100
SC-IO-360-B1F	\$16,100
SC-IO-360-B1G6	\$16,100
SC-IO-360-C1B	\$16,100
SC-IO-360-C1C	\$16,100
SC-IO-360-C1C6	\$16,100
SC-IO-360-C1D6	\$16,100
SC-IO-360-C1E6	\$16,100
SC-IO-360-C1F	\$16,100
SC-IO-360-C1G6	\$16,100
SC-IO-360-L2A	\$16,100
SC-IO-360-M1A	\$16,100
SC-IO-360-M1B	\$16,100
SC-IO-540-AA1A5	\$19,400
SC-IO-540-AA1B5	\$19,400
SC-IO-540-AB1A5	\$19,400
SC-IO-540-AC1A5	\$19,400
SC-IO-540-AE1A5	\$19,400
SC-IO-540-C1B5	\$19,400
SC-IO-540-C4B5	\$19,400
SC-IO-540-C4D5	\$19,400
SC-IO-540-C4D5D	\$19,400
SC-IO-540-D4A5	\$19,400
SC-IO-540-D4B5	\$19,400
SC-IO-540-G1D5	\$19,400
SC-IO-540-J4A5	\$19,400
SC-IO-540-K1A5	\$19,400
SC-IO-540-K1A5D	\$19,400
SC-IO-540-K1B5	\$19,400
SC-IO-540-K1D5	\$19,400
SC-IO-540-K1E5	\$19,400
SC-IO-540-K1F5	\$19,400
SC-IO-540-K1G5	\$19,400
SC-IO-540-K1G5D	\$19,400
SC-IO-540-K1J5	\$19,400
SC-IO-540-K1J5D	\$19,400
SC-IO-540-K1K5	\$19,400
SC-IO-540-L1C5	\$19,400
SC-IO-540-M1A5	\$19,400
SC-IO-540-M1B5D	\$19,400
SC-IO-540-M1C5	\$19,400
SC-IO-540-N1A5	\$19,400
SC-IO-540-R1A5	\$19,400
SC-IO-540-S1A5	\$19,400
SC-IO-540-T4A5D	\$19,400
SC-IO-540-T4B5	\$19,400
SC-IO-540-T4B5D	\$19,400

New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-IO-540-V4A5	\$21,870
NC-IO-540-W1A5	\$21,870
NC-IO-540-W1A5D	\$21,870
NC-IO-720-A1B	\$49,450
NC-IO-720-B1B	\$49,450
NC-IO-720-D1B	\$49,450
NC-IO-720-D1C	\$49,450
NC-LIO-320-B1A	\$17,560
NC-LIO-360-C1E6	\$18,560
NC-LIO-360-M1A	\$18,560
NC-LO-360-A1G6D	\$17,560
NC-LO-360-A1H6	\$17,560
NC-LO-360-E1A6D	\$17,560
NC-LTIO-540-F2BD	\$28,100
NC-LTIO-540-J2B	\$28,100
NC-LTIO-540-J2B	\$28,100
NC-LTIO-540-J2BD	\$28,100
NC-LTIO-540-U2A	\$35,500
NC-LTO-360-E1A6D	\$22,490
NC-O-235-C1	\$15,950
NC-O-235-C1B	\$15,950
NC-O-235-C2A	\$15,950
NC-O-235-C2C	\$15,950
NC-O-235-F2B	\$15,950
NC-O-235-H2C	\$15,950
NC-O-235-J2A	\$15,950
NC-O-235-K2B	\$15,950
NC-O-235-K2C	\$15,950
NC-O-235-L2A	\$15,950
NC-O-235-L2C	\$15,950
NC-O-235-N2A	\$15,950
NC-O-235-N2C	\$15,950
NC-O-320-A2A	\$17,260
NC-O-320-A2B	\$17,260
NC-O-320-A2C	\$17,260
NC-O-320-A2D	\$17,260
NC-O-320-A3A	\$17,260
NC-O-320-A3B	\$17,260
NC-O-320-B1A	\$17,260
NC-O-320-B2A	\$17,260
NC-O-320-B2B	\$17,260
NC-O-320-B2B	\$17,260
NC-O-320-B2C	\$17,260
NC-O-320-B2D	\$17,260
NC-O-320-B3B	\$17,260
NC-O-320-D1A	\$17,260
NC-O-320-D1D	\$17,260
NC-O-320-D1F	\$17,260

Select Exchange Engine Core	
Part Number	Value
SC-IO-540-V4A5	\$19,400
SC-IO-540-W1A5	\$19,400
SC-IO-540-W1A5D	\$19,400
SC-IO-720-A1B	N/A
SC-IO-720-B1B	N/A
SC-IO-720-D1B	N/A
SC-IO-720-D1C	N/A
SC-LIO-320-B1A	\$15,100
SC-LIO-360-C1E6	\$16,100
SC-LIO-360-M1A	\$16,100
SC-LO-360-A1G6D	\$15,100
SC-LO-360-A1H6	\$15,100
SC-LO-360-E1A6D	\$15,100
SC-LTIO-540-F2BD	\$23,900
SC-LTIO-540-J2B	\$23,900
SC-LTIO-540-J2B	\$23,900
SC-LTIO-540-J2BD	\$23,900
SC-LTIO-540-U2A	\$31,300
SC-LTO-360-E1A6D	\$18,300
SC-O-235-C1	\$14,100
SC-O-235-C1B	\$14,100
SC-O-235-C2A	\$14,100
SC-O-235-C2C	\$14,100
SC-O-235-F2B	\$14,100
SC-O-235-H2C	\$14,100
SC-O-235-J2A	\$14,100
SC-O-235-K2B	\$14,100
SC-O-235-K2C	\$14,100
SC-O-235-L2A	\$14,100
SC-O-235-L2C	\$14,100
SC-O-235-N2A	\$14,100
SC-O-235-N2C	\$14,100
SC-O-320-A2A	\$14,800
SC-O-320-A2B	\$14,800
SC-O-320-A2C	\$14,800
SC-O-320-A2D	\$14,800
SC-O-320-A3A	\$14,800
SC-O-320-A3B	\$14,800
SC-O-320-B1A	\$14,800
SC-O-320-B2A	\$14,800
SC-O-320-B2B	\$14,800
SC-O-320-B2B	\$14,800
SC-O-320-B2C	\$14,800
SC-O-320-B2D	\$14,800
SC-O-320-B3B	\$14,800
SC-O-320-D1A	\$14,800
SC-O-320-D1D	\$14,800
SC-O-320-D1F	\$14,800

New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-O-320-D2A	\$17,260
NC-O-320-D2B	\$17,260
NC-O-320-D2G	\$17,260
NC-O-320-D2J	\$17,260
NC-O-320-D3G	\$17,260
NC-O-320-D3G	\$17,260
NC-O-320-E2A	\$17,260
NC-O-320-E2C	\$17,260
NC-O-320-E2D	\$17,260
NC-O-320-E2F	\$17,260
NC-O-320-E2G	\$17,260
NC-O-320-E3D	\$17,260
NC-O-320-H2AD	\$17,260
NC-O-360-A1A	\$17,560
NC-O-360-A1AD	\$17,560
NC-O-360-A1D	\$17,560
NC-O-360-A1F6	\$17,560
NC-O-360-A1F6D	\$17,560
NC-O-360-A1G6D	\$17,560
NC-O-360-A1H6	\$17,560
NC-O-360-A1LD	\$17,560
NC-O-360-A1P	\$17,560
NC-O-360-A2A	\$17,560
NC-O-360-A2F	\$17,560
NC-O-360-A2G	\$17,560
NC-O-360-A3A	\$17,560
NC-O-360-A3AD	\$17,560
NC-O-360-A4A	\$17,560
NC-O-360-A4G	\$17,560
NC-O-360-A4J	\$17,560
NC-O-360-A4K	\$17,560
NC-O-360-A4M	\$17,560
NC-O-360-A4N	\$17,560
NC-O-360-A4P	\$17,560
NC-O-360-A5AD	\$17,560
NC-O-360-C1E	\$17,560
NC-O-360-C1F	\$17,560
NC-O-360-C1G	\$17,560
NC-O-360-C2A	\$17,560
NC-O-360-C2E	\$17,560
NC-O-360-C4F	\$17,560
NC-O-360-C4P	\$17,560
NC-O-360-E1A6D	\$17,560
NC-O-360-F1A6	\$17,560
NC-O-360-J2A	\$17,560
NC-O-540-A1A5	\$20,070
NC-O-540-A1B5	\$20,070
NC-O-540-A1C5	\$20,070

Select Exchange Engine Core	
Part Number	Value
SC-O-320-D2A	\$14,800
SC-O-320-D2B	\$14,800
SC-O-320-D2G	\$14,800
SC-O-320-D2J	\$14,800
SC-O-320-D3G	\$14,800
SC-O-320-D3G	\$14,800
SC-O-320-E2A	\$14,800
SC-O-320-E2C	\$14,800
SC-O-320-E2D	\$14,800
SC-O-320-E2F	\$14,800
SC-O-320-E2G	\$14,800
SC-O-320-E3D	\$14,800
SC-O-320-H2AD	\$14,800
SC-O-360-A1A	\$15,100
SC-O-360-A1AD	\$15,100
SC-O-360-A1D	\$15,100
SC-O-360-A1F6	\$15,100
SC-O-360-A1F6D	\$15,100
SC-O-360-A1G6D	\$15,100
SC-O-360-A1H6	\$15,100
SC-O-360-A1LD	\$15,100
SC-O-360-A1P	\$15,100
SC-O-360-A2A	\$15,100
SC-O-360-A2F	\$15,100
SC-O-360-A2G	\$15,100
SC-O-360-A3A	\$15,100
SC-O-360-A3AD	\$15,100
SC-O-360-A4A	\$15,100
SC-O-360-A4G	\$15,100
SC-O-360-A4J	\$15,100
SC-O-360-A4K	\$15,100
SC-O-360-A4M	\$15,100
SC-O-360-A4N	\$15,100
SC-O-360-A4P	\$15,100
SC-O-360-A5AD	\$15,100
SC-O-360-C1E	\$15,100
SC-O-360-C1F	\$15,100
SC-O-360-C1G	\$15,100
SC-O-360-C2A	\$15,100
SC-O-360-C2E	\$15,100
SC-O-360-C4F	\$15,100
SC-O-360-C4P	\$15,100
SC-O-360-E1A6D	\$15,100
SC-O-360-F1A6	\$15,100
SC-O-360-J2A	\$15,100
SC-O-540-A1A5	\$17,600
SC-O-540-A1B5	\$17,600
SC-O-540-A1C5	\$17,600

New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-O-540-A1D5	\$20,070
NC-O-540-A4D5	\$20,070
NC-O-540-B1A5	\$21,170
NC-O-540-B2B5	\$21,170
NC-O-540-B2C5	\$21,170
NC-O-540-B4B5	\$21,170
NC-O-540-E4A5	\$21,170
NC-O-540-E4B5	\$21,170
NC-O-540-E4C5	\$21,170
NC-O-540-F1B5	\$21,170
NC-O-540-G1A5	\$21,170
NC-O-540-H2A5	\$21,170
NC-O-540-J1A5D	\$21,170
NC-O-540-J3A5	\$21,170
NC-O-540-J3A5D	\$21,170
NC-O-540-J3C5D	\$21,170
NC-O-540-L3C5D	\$21,170
NC-TIO-360-C1A6D	\$22,490
NC-TIO-540-A2B	\$28,100
NC-TIO-540-A2C	\$28,100
NC-TIO-540-AA1AD	\$28,100
NC-TIO-540-AB1AD	\$28,100
NC-TIO-540-AB1BD	\$28,100
NC-TIO-540-AE2A	\$28,100
NC-TIO-540-AF1B	\$28,100
NC-TIO-540-AG1A	\$28,100
NC-TIO-540-AH1A	\$28,100
NC-TIO-540-AJ1A	\$28,100
NC-TIO-540-AK1A	\$28,100
NC-TIO-540-C1A	\$28,100
NC-TIO-540-F2BD	\$28,100
NC-TIO-540-J2B	\$28,100
NC-TIO-540-J2B	\$28,100
NC-TIO-540-J2BD	\$28,100
NC-TIO-540-S1AD	\$28,100
NC-TIO-540-U2A	\$35,500
NC-TIO-540-W2A	\$35,500
NC-TO-360-C1A6D	\$22,490
NC-TO-360-E1A6D	\$22,490

Select Exchange Engine Core	
Part Number	Value
SC-O-540-A1D5	\$17,600
SC-O-540-A4D5	\$17,600
SC-O-540-B1A5	\$18,700
SC-O-540-B2B5	\$18,700
SC-O-540-B2C5	\$18,700
SC-O-540-B4B5	\$18,700
SC-O-540-E4A5	\$18,700
SC-O-540-E4B5	\$18,700
SC-O-540-E4C5	\$18,700
SC-O-540-F1B5	\$18,700
SC-O-540-G1A5	\$18,700
SC-O-540-H2A5	\$18,700
SC-O-540-J1A5D	\$18,700
SC-O-540-J3A5	\$18,700
SC-O-540-J3A5D	\$18,700
SC-O-540-J3C5D	\$18,700
SC-O-540-L3C5D	\$18,700
SC-TIO-360-C1A6D	\$18,300
SC-TIO-540-A2B	\$23,900
SC-TIO-540-A2C	\$23,900
SC-TIO-540-AA1AD	\$23,900
SC-TIO-540-AB1AD	\$23,900
SC-TIO-540-AB1BD	\$23,900
SC-TIO-540-AE2A	\$23,900
SC-TIO-540-AF1B	\$23,900
SC-TIO-540-AG1A	\$23,900
SC-TIO-540-AH1A	\$23,900
SC-TIO-540-AJ1A	\$23,900
SC-TIO-540-AK1A	\$23,900
SC-TIO-540-C1A	\$23,900
SC-TIO-540-F2BD	\$23,900
SC-TIO-540-J2B	\$23,900
SC-TIO-540-J2B	\$23,900
SC-TIO-540-J2BD	\$23,900
SC-TIO-540-S1AD	\$23,900
SC-TIO-540-U2A	\$31,300
SC-TIO-540-W2A	\$31,300
SC-TO-360-C1A6D	\$18,300
SC-TO-360-E1A6D	\$18,300

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
O-235-C1	N/A	ENPL-9057	\$ 39,781	C	RENPL-9057	\$ 26,866	C	HENPL-9057	\$ 23,817	C	\$ 12,900
O-235-C1	N/A	ENPL-9080	\$ 39,157	C	RENPL-9080	\$ 26,267	C	HENPL-9080	\$ 23,218	C	\$ 12,900
O-235-C1	N/A	ENPL-9091	\$ 39,210	C	RENPL-9091	\$ 26,318	C	HENPL-9091	\$ 23,269	C	\$ 12,900
O-235-C1B	N/A	ENPL-9036	\$ 39,127	C	RENPL-9036	\$ 26,238	C	HENPL-9036	\$ 23,189	C	\$ 12,900
O-235-C1B	N/A	ENPL-9084	\$ 39,729	C	RENPL-9084	\$ 26,817	C	HENPL-9084	\$ 23,768	C	\$ 12,900
O-235-C2A	N/A	ENPL-9044	\$ 39,743	C	RENPL-9044	\$ 26,830	C	HENPL-9044	\$ 23,781	C	\$ 12,900
O-235-C2A	N/A	ENPL-9039	\$ 39,743	C	RENPL-9039	\$ 26,830	C	HENPL-9039	\$ 23,781	C	\$ 12,900
O-235-C2A	N/A	ENPL-9102	\$ 39,743	C	RENPL-9102	\$ 26,830	C	HENPL-9102	\$ 23,781	C	\$ 12,900
O-235-C2C	N/A	ENPL-9015	\$ 40,291	C	RENPL-9015	\$ 27,357	C	HENPL-9015	\$ 24,308	C	\$ 12,900
O-235-C2C	N/A	ENPL-9082	\$ 39,407	C	RENPL-9082	\$ 26,507	C	HENPL-9082	\$ 23,459	C	\$ 12,900
O-235-F2B	N/A	ENPL-9418	\$ 39,627	C	RENPL-9418	\$ 26,718	C	HENPL-9418	\$ 23,669	C	\$ 12,900
O-235-H2C	N/A	ENPL-6457	\$ 40,000	C	RENPL-6457	\$ 27,077	C	HENPL-6457	\$ 24,028	C	\$ 12,900
O-235-H2C	N/A	ENPL-9006	\$ 38,822	C	RENPL-9006	\$ 25,945	C	HENPL-9006	\$ 22,896	C	\$ 12,900
O-235-H2C	N/A	ENPL-9104	\$ 38,475	C	RENPL-9104	\$ 25,612	C	HENPL-9104	\$ 22,563	C	\$ 12,900
O-235-J2A	N/A	ENPL-9023	\$ 39,308	C	RENPL-9023	\$ 26,615	C	HENPL-9023	\$ 23,566	C	\$ 12,900
O-235-K2B	N/A	ENPL-9029	\$ 39,558	C	RENPL-9029	\$ 26,652	C	HENPL-9029	\$ 23,603	C	\$ 12,900
O-235-K2C	N/A	ENPL-6481	\$ 39,541	C	RENPL-6481	\$ 26,636	C	HENPL-6481	\$ 23,587	C	\$ 12,900
O-235-K2C	N/A	ENPL-9069	\$ 39,560	C	RENPL-9069	\$ 26,654	C	HENPL-9069	\$ 23,606	C	\$ 12,900
O-235-L2A	N/A	ENPL-6427	\$ 39,564	C	RENPL-6427	\$ 26,658	C	HENPL-6427	\$ 23,609	B	\$ 12,900
O-235-L2A	N/A	ENPL-9016	\$ 39,638	C	RENPL-9016	\$ 26,729	C	HENPL-9016	\$ 23,680	A	\$ 12,900
O-235-L2A	N/A	ENPL-9032	\$ 38,463	C	RENPL-9032	\$ 25,600	C	HENPL-9032	\$ 22,552	B	\$ 12,900
O-235-L2A	N/A	ENPL-9037	\$ 39,481	C	RENPL-9037	\$ 26,578	C	HENPL-9037	\$ 23,529	B	\$ 12,900
O-235-L2A	N/A	ENPL-9065	\$ 39,949	C	RENPL-9065	\$ 27,027	C	HENPL-9065	\$ 23,979	B	\$ 12,900
O-235-L2A	N/A	ENPL-9075	\$ 39,781	C	RENPL-9075	\$ 26,866	C	HENPL-9075	\$ 23,817	B	\$ 12,900
O-235-L2A	N/A	ENPL-9112	\$ 40,021	C	RENPL-9112	\$ 27,097	C	HENPL-9112	\$ 24,048	B	\$ 12,900
O-235-L2C	N/A	ENPL-6397	\$ 39,077	C	RENPL-6397	\$ 26,190	C	HENPL-6397	\$ 23,141	B	\$ 12,900
O-235-L2C	N/A	ENPL-6403	\$ 39,045	C	RENPL-6403	\$ 26,160	C	HENPL-6403	\$ 23,111	B	\$ 12,900
O-235-L2C	N/A	ENPL-6475	\$ 39,767	C	RENPL-6475	\$ 27,059	C	HENPL-6475	\$ 24,010	B	\$ 12,900
O-235-L2C	N/A	ENPL-6479	\$ 39,220	C	RENPL-6479	\$ 26,328	C	HENPL-6479	\$ 23,279	A	\$ 12,900
O-235-L2C	N/A	ENPL-9005	\$ 39,508	C	RENPL-9005	\$ 26,604	C	HENPL-9005	\$ 23,555	B	\$ 12,900
O-235-L2C	N/A	ENPL-9076	\$ 39,131	C	RENPL-9076	\$ 26,242	C	HENPL-9076	\$ 23,193	B	\$ 12,900
O-235-L2C	N/A	ENPL-9081	\$ 39,207	C	RENPL-9081	\$ 26,315	C	HENPL-9081	\$ 23,267	B	\$ 12,900
O-235-L2C	N/A	ENPL-9089	\$ 39,188	C	RENPL-9089	\$ 26,297	C	HENPL-9089	\$ 23,248	B	\$ 12,900
O-235-L2C	N/A	ENPL-9095	\$ 39,219	C	RENPL-9095	\$ 26,327	C	HENPL-9095	\$ 23,278	B	\$ 12,900
O-235-N2A	N/A	ENPL-9031	\$ 39,242	C	RENPL-9031	\$ 26,349	C	HENPL-9031	\$ 23,300	C	\$ 12,900
O-235-N2C	N/A	ENPL-9106	\$ 39,983	C	RENPL-9106	\$ 27,060	C	HENPL-9106	\$ 24,011	C	\$ 12,900
O-235-N2C	N/A	ENPL-6476	\$ 38,819	C	RENPL-6476	\$ 25,943	C	HENPL-6476	\$ 22,894	C	\$ 12,900
O-235-N2C	N/A	ENPL-9072	\$ 39,655	C	RENPL-9072	\$ 26,745	C	HENPL-9072	\$ 23,697	C	\$ 12,900
O-235-N2C	N/A	ENPL-9085	\$ 38,782	C	RENPL-9085	\$ 25,907	C	HENPL-9085	\$ 22,858	C	\$ 12,900
O-235-N2C	N/A	ENPL-9092	\$ 38,866	C	RENPL-9092	\$ 25,988	C	HENPL-9092	\$ 22,939	C	\$ 12,900
AEIO-320-D1B	YES	ENPL-RT8428	\$ 49,292	C	RENPL-RT8428	\$ 34,570	C	HENPL-RT8428	\$ 30,911	C	\$ 13,900
AEIO-320-D1B	YES	ENPL-RT9313	\$ 48,870	C	RENPL-RT9313	\$ 34,165	C	HENPL-RT9313	\$ 30,506	C	\$ 13,900
AEIO-320-D1B	YES	ENPL-RT9675	\$ 49,304	C	RENPL-RT9675	\$ 34,582	C	HENPL-RT9675	\$ 30,923	C	\$ 13,900
AEIO-320-D2B	YES	ENPL-RT9787	\$ 50,154	C	RENPL-RT9787	\$ 35,398	C	HENPL-RT9787	\$ 31,739	C	\$ 13,900
AEIO-320-E1B	YES	ENPL-RT8127	\$ 49,088	C	RENPL-RT8127	\$ 34,374	C	HENPL-RT8127	\$ 30,716	C	\$ 13,900
AEIO-320-E2B	YES	ENPL-RT8128	\$ 48,963	C	RENPL-RT8128	\$ 34,254	C	HENPL-RT8128	\$ 30,595	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT10053	\$ 46,144	C	RENPL-RT10053	\$ 31,546	C	HENPL-RT10053	\$ 27,888	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT8579	\$ 46,987	C	RENPL-RT8579	\$ 32,356	C	HENPL-RT8579	\$ 28,698	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT8710	\$ 46,416	C	RENPL-RT8710	\$ 31,808	C	HENPL-RT8710	\$ 28,149	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT9387	\$ 50,634	C	RENPL-RT9387	\$ 35,859	C	HENPL-RT9387	\$ 32,200	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT9525	\$ 46,559	C	RENPL-RT9525	\$ 31,945	C	HENPL-RT9525	\$ 28,286	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT9682	\$ 47,213	C	RENPL-RT9682	\$ 32,573	C	HENPL-RT9682	\$ 28,915	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT9982	\$ 47,208	C	RENPL-RT9982	\$ 32,568	C	HENPL-RT9982	\$ 28,910	C	\$ 13,900
IO-320-D1A	YES	ENPL-RT9846	\$ 46,621	C	RENPL-RT9846	\$ 32,005	C	HENPL-RT9846	\$ 28,346	C	\$ 13,900
IO-320-D1B	YES	ENPL-RT10021	\$ 46,360	C	RENPL-RT10021	\$ 31,753	C	HENPL-RT10021	\$ 28,094	C	\$ 13,900

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
IO-320-D1B	YES	ENPL-RT8787	\$ 46,136	C	RENPL-RT8787	\$ 31,538	C	HENPL-RT8787	\$ 27,880	C	\$ 13,900
IO-320-D1B	YES	ENPL-RT8907	\$ 47,148	C	RENPL-RT8907	\$ 32,510	C	HENPL-RT8907	\$ 28,852	C	\$ 13,900
IO-320-E1B	YES	ENPL-RT9741	\$ 46,750	C	RENPL-RT9741	\$ 32,128	C	HENPL-RT9741	\$ 28,469	C	\$ 13,900
IO-320-E2A	YES	ENPL-RT8557	\$ 46,657	C	RENPL-RT8557	\$ 32,039	C	HENPL-RT8557	\$ 28,381	C	\$ 13,900
IO-320-E2B	YES	ENPL-RT8862	\$ 46,715	C	RENPL-RT8862	\$ 32,095	C	HENPL-RT8862	\$ 28,436	C	\$ 13,900
LIO-320-B1A	YES	ENPL-RT8889	\$ 47,907	C	RENPL-RT8889	\$ 33,239	C	HENPL-RT8889	\$ 29,581	C	\$ 13,900
LIO-320-B1A	YES	ENPL-RT9638	\$ 47,417	C	RENPL-RT9638	\$ 32,769	C	HENPL-RT9638	\$ 29,111	C	\$ 13,900
LIO-320-B1A	YES	ENPL-RT9688	\$ 47,331	C	RENPL-RT9688	\$ 32,686	C	HENPL-RT9688	\$ 29,028	C	\$ 13,900
O-320-A2A	YES	ENPL-RT8989	\$ 42,945	C	RENPL-RT8989	\$ 28,884	C	HENPL-RT8989	\$ 25,225	C	\$ 13,600
O-320-A2B	YES	ENPL-RT10055	\$ 42,781	C	RENPL-RT10055	\$ 28,727	C	HENPL-RT10055	\$ 25,068	C	\$ 13,600
O-320-A2B	YES	ENPL-RT8553	\$ 41,713	C	RENPL-RT8553	\$ 27,793	C	HENPL-RT8553	\$ 24,135	C	\$ 13,600
O-320-A2B	YES	ENPL-RT8624	\$ 42,796	C	RENPL-RT8624	\$ 28,742	C	HENPL-RT8624	\$ 25,083	C	\$ 13,600
O-320-A2B	YES	ENPL-RT9379	\$ 42,963	C	RENPL-RT9379	\$ 28,901	C	HENPL-RT9379	\$ 25,243	C	\$ 13,600
O-320-A2B	YES	ENPL-RT9802	\$ 42,293	C	RENPL-RT9802	\$ 28,258	C	HENPL-RT9802	\$ 24,599	C	\$ 13,600
O-320-A2C	YES	ENPL-RT8821	\$ 43,076	C	RENPL-RT8821	\$ 29,010	C	HENPL-RT8821	\$ 25,352	C	\$ 13,600
O-320-A2D	YES	ENPL-RT8822	\$ 42,559	C	RENPL-RT8822	\$ 28,514	C	HENPL-RT8822	\$ 24,855	C	\$ 13,600
O-320-A3A	YES	ENPL-RT9393	\$ 43,218	C	RENPL-RT9393	\$ 29,146	C	HENPL-RT9393	\$ 25,488	C	\$ 13,600
O-320-A3B	YES	ENPL-RT9384	\$ 41,438	C	RENPL-RT9384	\$ 27,437	C	HENPL-RT9384	\$ 23,779	C	\$ 13,600
O-320-B1A	YES	ENPL-RT9467	\$ 42,942	C	RENPL-RT9467	\$ 28,881	C	HENPL-RT9467	\$ 25,223	C	\$ 13,600
O-320-B2A	YES	ENPL-RT9812	\$ 42,552	C	RENPL-RT9812	\$ 28,506	C	HENPL-RT9812	\$ 24,848	C	\$ 13,600
O-320-B2B	YES	ENPL-RT10067	\$ 41,896	C	RENPL-RT10067	\$ 27,877	C	HENPL-RT10067	\$ 24,219	C	\$ 13,600
O-320-B2B	YES	ENPL-RT8493	\$ 42,305	C	RENPL-RT8493	\$ 28,483	C	HENPL-RT8493	\$ 24,824	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9346	\$ 42,910	C	RENPL-RT9346	\$ 28,851	C	HENPL-RT9346	\$ 25,192	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9514	\$ 42,238	C	RENPL-RT9514	\$ 28,418	C	HENPL-RT9514	\$ 24,759	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9645	\$ 42,452	C	RENPL-RT9645	\$ 28,411	C	HENPL-RT9645	\$ 24,753	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9757	\$ 42,569	C	RENPL-RT9757	\$ 28,523	C	HENPL-RT9757	\$ 24,865	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9892	\$ 42,356	C	RENPL-RT9892	\$ 28,413	C	HENPL-RT9892	\$ 24,755	C	\$ 13,600
O-320-B2B**	YES	ENPL-RT10428	\$ 43,012	C	RENPL-RT10428	\$ 28,949	C	HENPL-RT10428	\$ 25,290	C	\$ 13,600
O-320-B2C	YES	ENPL-RT8864	\$ 42,764	C	RENPL-RT8864	\$ 28,927	C	HENPL-RT8864	\$ 25,269	C	\$ 13,600
O-320-B2C	YES	ENPL-RT8940	\$ 43,128	C	RENPL-RT8940	\$ 29,036	C	HENPL-RT8940	\$ 25,377	C	\$ 13,600
O-320-B2C	YES	ENPL-RT9752	\$ 43,128	C	RENPL-RT9752	\$ 29,524	C	HENPL-RT9752	\$ 25,865	C	\$ 13,600
O-320-B2C	YES	ENPL-RT9860	\$ 42,762	C	RENPL-RT9860	\$ 28,708	C	HENPL-RT9860	\$ 25,050	C	\$ 13,600
O-320-B2D	YES	ENPL-RT9487	\$ 42,075	C	RENPL-RT9487	\$ 28,049	C	HENPL-RT9487	\$ 24,390	C	\$ 13,600
O-320-B3B	YES	ENPL-RT10135	\$ 41,988	C	RENPL-RT10135	\$ 27,965	C	HENPL-RT10135	\$ 24,306	C	\$ 13,600
O-320-B3B	YES	ENPL-RT8587	\$ 42,496	C	RENPL-RT8587	\$ 28,453	C	HENPL-RT8587	\$ 24,795	C	\$ 13,600
O-320-B3B	YES	ENPL-RT9350	\$ 41,885	C	RENPL-RT9350	\$ 27,866	C	HENPL-RT9350	\$ 24,207	C	\$ 13,600
O-320-B3B	YES	ENPL-RT9850	\$ 42,646	C	RENPL-RT9850	\$ 28,597	C	HENPL-RT9850	\$ 24,938	C	\$ 13,600
O-320-B3B	YES	ENPL-RT9870	\$ 42,715	C	RENPL-RT9870	\$ 28,664	C	HENPL-RT9870	\$ 25,005	C	\$ 13,600
O-320-D1A	YES	ENPL-RT8508	\$ 42,086	C	RENPL-RT8508	\$ 28,059	C	HENPL-RT8508	\$ 24,400	C	\$ 13,600
O-320-D1A	YES	ENPL-RT8609	\$ 43,107	C	RENPL-RT8609	\$ 29,040	C	HENPL-RT8609	\$ 25,381	C	\$ 13,600
O-320-D1A	YES	ENPL-RT8760	\$ 42,567	C	RENPL-RT8760	\$ 28,521	C	HENPL-RT8760	\$ 24,863	C	\$ 13,600
O-320-D1A	YES	ENPL-RT8978	\$ 42,612	C	RENPL-RT8978	\$ 28,565	C	HENPL-RT8978	\$ 24,906	C	\$ 13,600
O-320-D1A	YES	ENPL-RT9650	\$ 43,396	C	RENPL-RT9650	\$ 29,317	C	HENPL-RT9650	\$ 25,659	C	\$ 13,600
O-320-D1A	YES	ENPL-RT10659	\$ 42,634	C	RENPL-RT10659	\$ 28,586	C	HENPL-RT10659	\$ 24,927	C	\$ 13,600
O-320-D1A	YES	ENPL-RT9314	\$ 42,828	C	RENPL-RT9314	\$ 28,772	C	HENPL-RT9314	\$ 25,114	C	\$ 13,600
O-320-D1D	YES	ENPL-RT8144	\$ 42,911	C	RENPL-RT8144	\$ 28,852	C	HENPL-RT8144	\$ 25,193	C	\$ 13,600
O-320-D1D	YES	ENPL-RT9776	\$ 43,059	C	RENPL-RT9776	\$ 28,994	C	HENPL-RT9776	\$ 25,336	C	\$ 13,600
O-320-D1F	YES	ENPL-RT8556	\$ 43,058	C	RENPL-RT8556	\$ 28,993	C	HENPL-RT8556	\$ 25,334	C	\$ 13,600
O-320-D1F	YES	ENPL-RT9454	\$ 43,136	C	RENPL-RT9454	\$ 29,068	C	HENPL-RT9454	\$ 25,409	C	\$ 13,600
O-320-D2A	YES	ENPL-RT10006	\$ 42,921	C	RENPL-RT10006	\$ 28,862	C	HENPL-RT10006	\$ 25,203	C	\$ 13,600
O-320-D2A	YES	ENPL-RT10354	\$ 42,823	C	RENPL-RT10354	\$ 28,767	C	HENPL-RT10354	\$ 25,108	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8421	\$ 41,887	C	RENPL-RT8421	\$ 28,542	C	HENPL-RT8421	\$ 24,884	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8438	\$ 42,887	C	RENPL-RT8438	\$ 28,828	C	HENPL-RT8438	\$ 25,170	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8551	\$ 42,932	C	RENPL-RT8551	\$ 28,872	C	HENPL-RT8551	\$ 25,213	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8562	\$ 42,848	C	RENPL-RT8562	\$ 28,791	C	HENPL-RT8562	\$ 25,133	C	\$ 13,600

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURES SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
O-320-D2A	YES	ENPL-RT8589	\$ 42,324	C	RENPL-RT8589	\$ 28,287	C	HENPL-RT8589	\$ 24,629	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8596	\$ 42,937	C	RENPL-RT8596	\$ 28,877	C	HENPL-RT8596	\$ 25,218	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8610	\$ 42,925	C	RENPL-RT8610	\$ 28,865	C	HENPL-RT8610	\$ 25,207	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8748	\$ 42,865	C	RENPL-RT8748	\$ 28,807	C	HENPL-RT8748	\$ 25,149	C	\$ 13,600
O-320-D2A	YES	ENPL-RT9634	\$ 42,438	C	RENPL-RT9634	\$ 28,849	C	HENPL-RT9634	\$ 25,190	C	\$ 13,600
O-320-D2A	YES	ENPL-RT9676	\$ 42,473	C	RENPL-RT9676	\$ 28,431	C	HENPL-RT9676	\$ 24,772	C	\$ 13,600
O-320-D2A	YES	ENPL-RT9767	\$ 42,427	C	RENPL-RT9767	\$ 28,386	C	HENPL-RT9767	\$ 24,728	C	\$ 13,600
O-320-D2A	YES	ENPL-RT9923	\$ 43,325	C	RENPL-RT9923	\$ 29,249	C	HENPL-RT9923	\$ 25,591	C	\$ 13,600
O-320-D2A *	YES	ENPL-RT10359	\$ 42,127	C	RENPL-RT10359	\$ 28,099	C	HENPL-RT10359	\$ 24,440	C	\$ 13,600
O-320-D2B	YES	ENPL-RT8625	\$ 42,360	C	RENPL-RT8625	\$ 28,322	C	HENPL-RT8625	\$ 24,664	C	\$ 13,600
O-320-D2G	YES	ENPL-RT10156	\$ 41,806	C	RENPL-RT10156	\$ 27,790	C	HENPL-RT10156	\$ 24,131	C	\$ 13,600
O-320-D2G	YES	ENPL-RT10182	\$ 42,224	C	RENPL-RT10182	\$ 28,192	C	HENPL-RT10182	\$ 24,534	C	\$ 13,600
O-320-D2G	YES	ENPL-RT8024	\$ 42,166	C	RENPL-RT8024	\$ 28,136	C	HENPL-RT8024	\$ 24,478	C	\$ 13,600
O-320-D2G	YES	ENPL-RT8372	\$ 42,175	C	RENPL-RT8372	\$ 28,145	C	HENPL-RT8372	\$ 24,487	C	\$ 13,600
O-320-D2G *	YES	ENPL-RT10240	\$ 41,777	C	RENPL-RT10240	\$ 27,763	C	HENPL-RT10240	\$ 24,104	C	\$ 13,600
O-320-D2J	YES	ENPL-RT10153	\$ 41,728	C	RENPL-RT10153	\$ 27,715	C	HENPL-RT10153	\$ 24,057	B	\$ 13,600
O-320-D2J	YES	ENPL-RT8164	\$ 41,757	C	RENPL-RT8164	\$ 27,743	C	HENPL-RT8164	\$ 24,085	A	\$ 13,600
O-320-D2J	YES	ENPL-RT8373	\$ 41,738	C	RENPL-RT8373	\$ 27,933	C	HENPL-RT8373	\$ 24,275	B	\$ 13,600
O-320-D2J	YES	ENPL-RT9677	\$ 42,034	C	RENPL-RT9677	\$ 28,009	C	HENPL-RT9677	\$ 24,351	B	\$ 13,600
O-320-D2J	YES	ENPL-RT9864	\$ 42,344	C	RENPL-RT9864	\$ 28,307	C	HENPL-RT9864	\$ 24,649	B	\$ 13,600
O-320-D2J	YES	ENPL-RT10640	\$ 42,078	C	RENPL-RT10640	\$ 28,052	C	HENPL-RT10640	\$ 24,393	B	\$ 13,600
O-320-D2J	YES	ENPL-RT10681	\$ 42,034	C	RENPL-RT10681	\$ 28,009	C	HENPL-RT10681	\$ 24,351	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10078	\$ 42,984	C	RENPL-RT10078	\$ 28,922	C	HENPL-RT10078	\$ 25,263	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10180	\$ 42,432	C	RENPL-RT10180	\$ 28,439	C	HENPL-RT10180	\$ 24,780	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10316	\$ 44,059	C	RENPL-RT10316	\$ 29,955	C	HENPL-RT10316	\$ 26,296	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10345	\$ 43,068	C	RENPL-RT10345	\$ 29,003	C	HENPL-RT10345	\$ 25,344	B	\$ 13,600
O-320-D3G	YES	ENPL-RT8150	\$ 41,820	C	RENPL-RT8150	\$ 27,804	C	HENPL-RT8150	\$ 24,145	A	\$ 13,600
O-320-D3G	YES	ENPL-RT8446	\$ 42,287	C	RENPL-RT8446	\$ 28,252	C	HENPL-RT8446	\$ 24,594	B	\$ 13,600
O-320-D3G	YES	ENPL-RT8585	\$ 42,300	C	RENPL-RT8585	\$ 28,264	C	HENPL-RT8585	\$ 24,606	B	\$ 13,600
O-320-D3G	YES	ENPL-RT8885	\$ 41,743	C	RENPL-RT8885	\$ 27,730	C	HENPL-RT8885	\$ 24,072	B	\$ 13,600
O-320-D3G	YES	ENPL-RT9649	\$ 43,521	C	RENPL-RT9649	\$ 29,437	C	HENPL-RT9649	\$ 25,779	B	\$ 13,600
O-320-D3G	YES	ENPL-RT9792	\$ 42,875	C	RENPL-RT9792	\$ 28,817	C	HENPL-RT9792	\$ 25,159	B	\$ 13,600
O-320-D3G	YES	ENPL-RT9905	\$ 42,992	C	RENPL-RT9905	\$ 28,929	C	HENPL-RT9905	\$ 25,271	B	\$ 13,600
O-320-D3G	YES	ENPL-RT9910	\$ 42,833	C	RENPL-RT9910	\$ 28,777	C	HENPL-RT9910	\$ 25,118	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10300	\$ 42,687	C	RENPL-RT10300	\$ 28,637	C	HENPL-RT10300	\$ 24,978	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10445	\$ 42,349	C	RENPL-RT10445	\$ 28,311	C	HENPL-RT10445	\$ 24,653	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10447	\$ 40,880	C	RENPL-RT10447	\$ 27,995	C	HENPL-RT10447	\$ 24,336	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10571	\$ 41,467	C	RENPL-RT10571	\$ 27,463	C	HENPL-RT10571	\$ 23,805	B	\$ 13,600
O-320-D3G *	YES	ENPL-RT10172	\$ 41,309	C	RENPL-RT10172	\$ 27,312	C	HENPL-RT10172	\$ 23,653	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10701	\$ 43,275	C	RENPL-RT10701	\$ 29,201	C	HENPL-RT10701	\$ 25,543	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10665	\$ 47,446	C	RENPL-RT10665	\$ 32,612	C	HENPL-RT10665	\$ 28,953	B	\$ 13,600
O-320-E2A	YES	ENPL-RT8590	\$ 42,371	C	RENPL-RT8590	\$ 28,333	C	HENPL-RT8590	\$ 24,675	C	\$ 13,600
O-320-E2A	YES	ENPL-RT8611	\$ 42,994	C	RENPL-RT8611	\$ 28,931	C	HENPL-RT8611	\$ 25,272	C	\$ 13,600
O-320-E2A	YES	ENPL-RT8626	\$ 43,278	C	RENPL-RT8626	\$ 29,205	C	HENPL-RT8626	\$ 25,546	C	\$ 13,600
O-320-E2A	YES	ENPL-RT8903	\$ 42,371	C	RENPL-RT8903	\$ 28,333	C	HENPL-RT8903	\$ 24,675	C	\$ 13,600
O-320-E2A	YES	ENPL-RT8923	\$ 42,993	C	RENPL-RT8923	\$ 28,931	C	HENPL-RT8923	\$ 25,273	C	\$ 13,600
O-320-E2A	YES	ENPL-RT9321	\$ 42,947	C	RENPL-RT9321	\$ 28,886	C	HENPL-RT9321	\$ 25,228	C	\$ 13,600
O-320-E2A	YES	ENPL-RT9744	\$ 42,516	C	RENPL-RT9744	\$ 28,472	C	HENPL-RT9744	\$ 24,813	C	\$ 13,600
O-320-E2C	YES	ENPL-RT10164	\$ 42,950	C	RENPL-RT10164	\$ 28,889	C	HENPL-RT10164	\$ 25,230	C	\$ 13,600
O-320-E2C	YES	ENPL-RT8564	\$ 43,276	C	RENPL-RT8564	\$ 29,202	C	HENPL-RT8564	\$ 25,544	C	\$ 13,600
O-320-E2D	YES	ENPL-RT10495	\$ 42,502	C	RENPL-RT10495	\$ 28,197	C	HENPL-RT10495	\$ 24,538	B	\$ 13,600
O-320-E2D	YES	ENPL-RT8031	\$ 42,171	C	RENPL-RT8031	\$ 28,188	C	HENPL-RT8031	\$ 24,530	B	\$ 13,600
O-320-E2D	YES	ENPL-RT8181	\$ 41,536	C	RENPL-RT8181	\$ 27,565	C	HENPL-RT8181	\$ 23,907	A	\$ 13,600
O-320-E2D	YES	ENPL-RT8797	\$ 42,626	C	RENPL-RT8797	\$ 28,578	C	HENPL-RT8797	\$ 24,920	B	\$ 13,600
O-320-E2D	YES	ENPL-RT8888	\$ 42,104	C	RENPL-RT8888	\$ 28,077	C	HENPL-RT8888	\$ 24,418	B	\$ 13,600

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
O-320-E2D	YES	ENPL-RT9668	\$ 42,280	C	RENPL-RT9668	\$ 28,245	C	HENPL-RT9668	\$ 24,587	B	\$ 13,600
O-320-E2D	YES	ENPL-RT9695	\$ 42,774	C	RENPL-RT9695	\$ 28,721	C	HENPL-RT9695	\$ 25,062	B	\$ 13,600
O-320-E2D	YES	ENPL-RT9794	\$ 42,424	C	RENPL-RT9794	\$ 28,384	C	HENPL-RT9794	\$ 24,725	B	\$ 13,600
O-320-E2D	YES	ENPL-RT9820	\$ 42,254	C	RENPL-RT9820	\$ 28,221	C	HENPL-RT9820	\$ 24,562	B	\$ 13,600
O-320-E2D	YES	ENPL-RT9847	\$ 42,424	C	RENPL-RT9847	\$ 28,384	C	HENPL-RT9847	\$ 24,725	B	\$ 13,600
O-320-E2D	YES	ENPL-RT9947	\$ 42,171	C	RENPL-RT9947	\$ 28,141	C	HENPL-RT9947	\$ 24,483	B	\$ 13,600
O-320-E2D *	YES	ENPL-RT10213	\$ 41,732	C	RENPL-RT10213	\$ 27,719	C	HENPL-RT10213	\$ 24,061	B	\$ 13,600
O-320-E2F	YES	ENPL-RT9619	\$ 42,413	C	RENPL-RT9619	\$ 28,373	C	HENPL-RT9619	\$ 24,714	C	\$ 13,600
O-320-E2G	YES	ENPL-RT8092	\$ 41,699	C	RENPL-RT8092	\$ 28,126	C	HENPL-RT8092	\$ 24,468	C	\$ 13,600
O-320-E2G	YES	ENPL-RT9738	\$ 42,327	C	RENPL-RT9738	\$ 28,291	C	HENPL-RT9738	\$ 24,632	C	\$ 13,600
O-320-E3D	YES	ENPL-RT8032	\$ 42,066	C	RENPL-RT8032	\$ 28,040	C	HENPL-RT8032	\$ 24,382	C	\$ 13,600
O-320-E3D	YES	ENPL-RT8310	\$ 41,659	C	RENPL-RT8310	\$ 27,857	C	HENPL-RT8310	\$ 24,198	C	\$ 13,600
O-320-E3D	YES	ENPL-RT9546	\$ 41,803	C	RENPL-RT9546	\$ 27,788	C	HENPL-RT9546	\$ 24,129	C	\$ 13,600
O-320-E3D	YES	ENPL-RT9665	\$ 42,012	C	RENPL-RT9665	\$ 27,989	C	HENPL-RT9665	\$ 24,330	C	\$ 13,600
O-320-E3D	YES	ENPL-RT9773	\$ 42,166	C	RENPL-RT9773	\$ 28,136	C	HENPL-RT9773	\$ 24,477	C	\$ 13,600
O-320-H2AD	N/A	ENPL-10282	\$ 44,338	C	RENPL-10282	\$ 30,145	C	HENPL-10282	\$ 26,487	B	\$ 13,600
O-320-H2AD	N/A	ENPL-7259	\$ 45,256	C	RENPL-7259	\$ 31,104	C	HENPL-7259	\$ 27,445	B	\$ 13,600
O-320-H2AD	N/A	ENPL-7396	\$ 44,363	C	RENPL-7396	\$ 30,247	C	HENPL-7396	\$ 26,588	A	\$ 13,600
O-320-H2AD	N/A	ENPL-7403	\$ 44,406	C	RENPL-7403	\$ 30,288	C	HENPL-7403	\$ 26,629	B	\$ 13,600
O-320-H2AD	N/A	ENPL-9837	\$ 44,566	C	RENPL-9837	\$ 30,441	C	HENPL-9837	\$ 26,783	B	\$ 13,600
O-320-H2AD	N/A	ENPL-9852	\$ 44,780	C	RENPL-9852	\$ 30,647	C	HENPL-9852	\$ 26,988	B	\$ 13,600
AEIO-360-A1A	YES	ENPL-RT8117	\$ 54,446	C	RENPL-RT8117	\$ 37,671	C	HENPL-RT8117	\$ 34,013	C	\$ 15,200
AEIO-360-A1B	YES	ENPL-RT8510	\$ 54,538	C	RENPL-RT8510	\$ 37,760	C	HENPL-RT8510	\$ 34,101	C	\$ 15,200
AEIO-360-A1B6	YES	ENPL-RT8524	\$ 55,233	C	RENPL-RT8524	\$ 38,427	C	HENPL-RT8524	\$ 34,769	C	\$ 15,200
AEIO-360-A1B6	YES	ENPL-RT8592	\$ 55,590	C	RENPL-RT8592	\$ 38,770	C	HENPL-RT8592	\$ 35,112	C	\$ 15,200
AEIO-360-A1B6	YES	ENPL-RT9363	\$ 55,275	C	RENPL-RT9363	\$ 38,468	C	HENPL-RT9363	\$ 34,809	C	\$ 15,200
AEIO-360-A1D	YES	ENPL-RT8665	\$ 53,553	C	RENPL-RT8665	\$ 36,814	C	HENPL-RT8665	\$ 33,155	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT8516	\$ 54,413	C	RENPL-RT8516	\$ 37,640	C	HENPL-RT8516	\$ 33,981	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT8526	\$ 53,552	C	RENPL-RT8526	\$ 36,813	C	HENPL-RT8526	\$ 33,154	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT9370	\$ 54,672	C	RENPL-RT9370	\$ 37,888	C	HENPL-RT9370	\$ 34,230	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT9533	\$ 54,413	C	RENPL-RT9533	\$ 37,640	C	HENPL-RT9533	\$ 33,981	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT9719	\$ 54,062	C	RENPL-RT9719	\$ 37,303	C	HENPL-RT9719	\$ 33,644	C	\$ 15,200
AEIO-360-A2C	YES	ENPL-RT9462	\$ 60,563	C	RENPL-RT9462	\$ 43,547	C	HENPL-RT9462	\$ 39,888	C	\$ 15,200
AEIO-360-B1B	YES	ENPL-RT8300	\$ 54,078	C	RENPL-RT8300	\$ 37,318	C	HENPL-RT8300	\$ 33,659	C	\$ 15,200
AEIO-360-B1F	YES	ENPL-RT10555	\$ 56,737	C	RENPL-RT10555	\$ 40,185	C	HENPL-RT10555	\$ 36,526	C	\$ 15,200
AEIO-360-B1F	YES	ENPL-RT7304	\$ 53,734	C	RENPL-RT7304	\$ 37,276	C	HENPL-RT7304	\$ 33,617	C	\$ 15,200
AEIO-360-B1F	YES	ENPL-RT8432	\$ 53,756	C	RENPL-RT8432	\$ 37,297	C	HENPL-RT8432	\$ 33,638	C	\$ 15,200
AEIO-360-B1F	YES	ENPL-RT9771	\$ 55,479	C	RENPL-RT9771	\$ 38,966	C	HENPL-RT9771	\$ 35,308	C	\$ 15,200
AEIO-360-B1G6	YES	ENPL-RT8445	\$ 54,368	C	RENPL-RT8445	\$ 37,596	C	HENPL-RT8445	\$ 33,938	C	\$ 15,200
AEIO-360-B1H	YES	ENPL-RT9574	\$ 53,963	C	RENPL-RT9574	\$ 37,207	C	HENPL-RT9574	\$ 33,549	C	\$ 15,200
AEIO-360-B1H	YES	ENPL-RT9575	\$ 54,347	C	RENPL-RT9575	\$ 37,577	C	HENPL-RT9575	\$ 33,918	C	\$ 15,200
AEIO-360-B2F	YES	ENPL-RT8661	\$ 52,630	C	RENPL-RT8661	\$ 35,927	C	HENPL-RT8661	\$ 32,268	C	\$ 15,200
AEIO-360-B2F	YES	ENPL-RT8769	\$ 51,693	C	RENPL-RT8769	\$ 35,028	C	HENPL-RT8769	\$ 31,369	C	\$ 15,200
AEIO-360-B4A	YES	ENPL-RT8844	\$ 53,505	C	RENPL-RT8844	\$ 36,767	C	HENPL-RT8844	\$ 33,109	C	\$ 15,200
AEIO-360-H1A	YES	ENPL-RT8633	\$ 53,298	C	RENPL-RT8633	\$ 36,569	C	HENPL-RT8633	\$ 32,910	C	\$ 15,200
AEIO-360-H1A	YES	ENPL-RT9765	\$ 53,467	C	RENPL-RT9765	\$ 36,732	C	HENPL-RT9765	\$ 33,073	C	\$ 15,200
AEIO-360-H1A *	YES	ENPL-RT9984	\$ 52,877	C	RENPL-RT9984	\$ 36,165	C	HENPL-RT9984	\$ 32,506	C	\$ 15,200
AEIO-360-H1B	YES	ENPL-RT10057	\$ 54,347	C	RENPL-RT10057	\$ 37,577	C	HENPL-RT10057	\$ 33,918	C	\$ 15,200
HIO-360-A1A	YES	ENPL-RT6879	\$ 63,072	C	RENPL-RT6879	\$ 45,957	C	HENPL-RT6879	\$ 42,298	C	\$ 15,200
HIO-360-B1A	YES	ENPL-RT9443	\$ 59,491	C	RENPL-RT9443	\$ 42,517	C	HENPL-RT9443	\$ 38,859	C	\$ 15,200
HIO-360-B1A	YES	ENPL-RT9874	\$ 59,450	C	RENPL-RT9874	\$ 42,478	C	HENPL-RT9874	\$ 38,820	C	\$ 15,200
HIO-360-C1A	N/A	ENPL-RT7287	\$ 60,409	C	RENPL-RT7287	\$ 43,054	C	HENPL-RT7287	\$ 39,395	C	\$ 15,200
HIO-360-C1A	N/A	ENPL-9985	\$ 58,865	C	RENPL-9985	\$ 41,916	C	HENPL-9985	\$ 38,257	C	\$ 15,200
HIO-360-C1B	YES	ENPL-RT9891	\$ 57,804	C	RENPL-RT9891	\$ 40,897	C	HENPL-RT9891	\$ 37,238	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-10007	\$ 56,170	C	RENPL-10007	\$ 39,327	C	HENPL-10007	\$ 35,669	C	\$ 15,200

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURES SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
HIO-360-D1A	N/A	ENPL-10161	\$ 55,782	C	RENPL-10161	\$ 38,954	C	HENPL-10161	\$ 35,296	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-10208	\$ 55,801	C	RENPL-10208	\$ 38,973	C	HENPL-10208	\$ 35,315	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-10253	\$ 55,933	C	RENPL-10253	\$ 39,099	C	HENPL-10253	\$ 35,441	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-7486	\$ 55,908	C	RENPL-7486	\$ 39,076	C	HENPL-7486	\$ 35,417	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-7497	\$ 55,863	C	RENPL-7497	\$ 39,032	C	HENPL-7497	\$ 35,374	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-8996	\$ 56,632	C	RENPL-8996	\$ 39,771	C	HENPL-8996	\$ 36,113	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-9372	\$ 56,223	C	RENPL-9372	\$ 39,378	C	HENPL-9372	\$ 35,720	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-9431	\$ 55,970	C	RENPL-9431	\$ 39,136	C	HENPL-9431	\$ 35,477	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-9867	\$ 55,554	C	RENPL-9867	\$ 38,736	C	HENPL-9867	\$ 35,078	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-9945	\$ 55,821	C	RENPL-9945	\$ 38,992	C	HENPL-9945	\$ 35,334	C	\$ 15,200
HIO-360-D1A ***	N/A	ENPL-9477	\$ 57,301	C	RENPL-9477	\$ 40,414	C	HENPL-9477	\$ 36,755	C	\$ 15,200
HIO-360-E1AD	N/A	ENPL-6819	\$ 58,690	D	RENPL-6819	\$ 41,748	D	HENPL-6819	\$ 38,090	D	\$ 15,200
HIO-360-E1AD	N/A	ENPL-9630	\$ 58,804	D	RENPL-9630	\$ 41,857	D	HENPL-9630	\$ 38,199	D	\$ 15,200
HIO-360-E1BD	N/A	ENPL-7022	\$ 58,508	D	RENPL-7022	\$ 41,573	D	HENPL-7022	\$ 37,914	D	\$ 15,200
HIO-360-E1BD	N/A	ENPL-9769	\$ 58,781	D	RENPL-9769	\$ 41,835	D	HENPL-9769	\$ 38,177	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-10041	\$ 58,131	D	RENPL-10041	\$ 41,211	D	HENPL-10041	\$ 37,552	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-10141	\$ 58,792	D	RENPL-10141	\$ 41,846	D	HENPL-10141	\$ 38,188	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-10557	\$ 59,121	D	RENPL-10557	\$ 42,162	D	HENPL-10557	\$ 38,503	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-8689	\$ 59,169	D	RENPL-8689	\$ 42,912	D	HENPL-8689	\$ 39,253	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-9818	\$ 59,116	D	RENPL-9818	\$ 42,157	D	HENPL-9818	\$ 38,498	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-9902	\$ 59,470	D	RENPL-9902	\$ 42,497	D	HENPL-9902	\$ 38,839	D	\$ 15,200
HIO-360-G1A	YES	ENPL-RT10152	\$ 48,761	C	RENPL-RT10152	\$ 32,211	C	HENPL-RT10152	\$ 28,553	C	\$ 15,200
HO-360-C1A	YES	ENPL-RT9396	\$ 48,633	C	RENPL-RT9396	\$ 33,937	C	HENPL-RT9396	\$ 30,279	C	\$ 13,900
HO-360-C1A	YES	ENPL-RT9707	\$ 48,633	C	RENPL-RT9707	\$ 33,937	C	HENPL-RT9707	\$ 30,279	C	\$ 13,900
HO-360-C1A	YES	ENPL-RT9881	\$ 48,369	C	RENPL-RT9881	\$ 33,683	C	HENPL-RT9881	\$ 30,025	C	\$ 13,900
HO-360-C1A	YES	ENPL-RT9946	\$ 48,535	C	RENPL-RT9946	\$ 33,842	C	HENPL-RT9946	\$ 30,184	C	\$ 13,900
IO-360-A1A	YES	ENPL-RT0441	\$ 53,590	C	RENPL-RT10441	\$ 37,260	C	HENPL-RT10441	\$ 33,602	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT8591	\$ 50,577	C	RENPL-RT8591	\$ 34,366	C	HENPL-RT8591	\$ 30,708	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT8668	\$ 50,337	C	RENPL-RT8668	\$ 34,135	C	HENPL-RT8668	\$ 30,477	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT8990	\$ 50,609	C	RENPL-RT8990	\$ 34,396	C	HENPL-RT8990	\$ 30,738	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT9635	\$ 50,736	C	RENPL-RT9635	\$ 34,519	C	HENPL-RT9635	\$ 30,860	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT9774	\$ 50,245	C	RENPL-RT9774	\$ 34,047	C	HENPL-RT9774	\$ 30,388	C	\$ 14,900
IO-360-A1B	YES	ENPL-RT10287	\$ 50,471	C	RENPL-RT10287	\$ 34,264	C	HENPL-RT10287	\$ 30,606	C	\$ 14,900
IO-360-A1B	YES	ENPL-RT9383	\$ 50,678	C	RENPL-RT9383	\$ 34,463	C	HENPL-RT9383	\$ 30,804	C	\$ 14,900
IO-360-A1B	YES	ENPL-RT9584	\$ 50,466	C	RENPL-RT9584	\$ 34,259	C	HENPL-RT9584	\$ 30,601	C	\$ 14,900
IO-360-A1B	YES	ENPL-RT9937	\$ 50,214	C	RENPL-RT9937	\$ 34,017	C	HENPL-RT9937	\$ 30,358	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10330	\$ 51,369	C	RENPL-RT10330	\$ 34,786	C	HENPL-RT10330	\$ 31,127	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10496	\$ 51,859	C	RENPL-RT10496	\$ 34,638	C	HENPL-RT10496	\$ 30,979	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10587	\$ 50,971	C	RENPL-RT10587	\$ 34,736	C	HENPL-RT10587	\$ 31,078	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10602	\$ 51,479	C	RENPL-RT10602	\$ 35,224	C	HENPL-RT10602	\$ 31,566	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10693	\$ 52,939	C	RENPL-RT10693	\$ 35,644	C	HENPL-RT10693	\$ 31,985	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8620	\$ 51,854	C	RENPL-RT8620	\$ 35,584	C	HENPL-RT8620	\$ 31,926	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8622	\$ 51,221	C	RENPL-RT8622	\$ 35,247	C	HENPL-RT8622	\$ 31,588	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8669	\$ 51,892	C	RENPL-RT8669	\$ 35,621	C	HENPL-RT8669	\$ 31,962	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8904	\$ 51,536	C	RENPL-RT8904	\$ 35,278	C	HENPL-RT8904	\$ 31,620	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8915	\$ 52,016	C	RENPL-RT8915	\$ 35,740	C	HENPL-RT8915	\$ 32,081	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9344	\$ 50,796	C	RENPL-RT9344	\$ 34,924	C	HENPL-RT9344	\$ 31,266	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9352	\$ 51,734	C	RENPL-RT9352	\$ 35,469	C	HENPL-RT9352	\$ 31,810	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9362	\$ 53,127	C	RENPL-RT9362	\$ 36,807	C	HENPL-RT9362	\$ 33,148	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9390	\$ 52,625	C	RENPL-RT9390	\$ 36,607	C	HENPL-RT9390	\$ 32,949	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9400	\$ 51,882	C	RENPL-RT9400	\$ 35,611	C	HENPL-RT9400	\$ 31,952	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9503	\$ 51,882	C	RENPL-RT9503	\$ 35,611	C	HENPL-RT9503	\$ 31,952	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9536	\$ 51,615	C	RENPL-RT9536	\$ 35,355	C	HENPL-RT9536	\$ 31,696	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9555	\$ 51,882	C	RENPL-RT9555	\$ 35,611	C	HENPL-RT9555	\$ 31,952	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9737	\$ 53,219	C	RENPL-RT9737	\$ 36,773	C	HENPL-RT9737	\$ 33,115	C	\$ 14,900

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
IO-360-A1B6	YES	ENPL-RT9768	\$ 51,799	C	RENPL-RT9768	\$ 35,531	C	HENPL-RT9768	\$ 31,873	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9882	\$ 51,922	C	RENPL-RT9882	\$ 35,649	C	HENPL-RT9882	\$ 31,991	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9896	\$ 50,435	C	RENPL-RT9896	\$ 34,486	C	HENPL-RT9896	\$ 30,827	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9943	\$ 51,879	C	RENPL-RT9943	\$ 35,608	C	HENPL-RT9943	\$ 31,950	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9999	\$ 52,215	C	RENPL-RT9999	\$ 35,930	C	HENPL-RT9999	\$ 32,272	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT10036	\$ 54,326	C	RENPL-RT10036	\$ 37,959	C	HENPL-RT10036	\$ 34,300	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT5655	\$ 54,222	C	RENPL-RT5655	\$ 37,858	C	HENPL-RT5655	\$ 34,200	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT8074	\$ 53,839	C	RENPL-RT8074	\$ 37,491	C	HENPL-RT8074	\$ 33,832	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT8548	\$ 54,736	C	RENPL-RT8548	\$ 38,353	C	HENPL-RT8548	\$ 34,694	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT8586	\$ 54,735	C	RENPL-RT8586	\$ 38,351	C	HENPL-RT8586	\$ 34,693	C	\$ 14,900
IO-360-A1D	YES	ENPL-RT4251	\$ 50,832	C	RENPL-RT4251	\$ 34,602	C	HENPL-RT4251	\$ 30,944	C	\$ 14,900
IO-360-A1D6	YES	ENPL-RT10333	\$ 52,218	C	RENPL-RT10333	\$ 35,934	C	HENPL-RT10333	\$ 32,275	C	\$ 14,900
IO-360-A1D6	YES	ENPL-RT9481	\$ 52,218	C	RENPL-RT9481	\$ 35,934	C	HENPL-RT9481	\$ 32,276	C	\$ 14,900
IO-360-A2B	YES	ENPL-RT8652	\$ 51,921	C	RENPL-RT8652	\$ 35,649	C	HENPL-RT8652	\$ 31,990	C	\$ 14,900
IO-360-A2B	YES	ENPL-RT9759	\$ 52,032	C	RENPL-RT9759	\$ 35,755	C	HENPL-RT9759	\$ 32,096	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT10027	\$ 52,419	C	RENPL-RT10027	\$ 36,127	C	HENPL-RT10027	\$ 32,468	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT10032	\$ 52,381	C	RENPL-RT10032	\$ 36,091	C	HENPL-RT10032	\$ 32,432	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT10502	\$ 52,816	C	RENPL-RT-10502	\$ 36,509	C	HENPL-10502	\$ 32,850	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT9304	\$ 52,840	C	RENPL-RT9304	\$ 36,532	C	HENPL-RT9304	\$ 32,873	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT9452	\$ 50,756	C	RENPL-RT9452	\$ 35,686	C	HENPL-RT9452	\$ 32,027	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT9479	\$ 52,052	C	RENPL-RT9479	\$ 35,774	C	HENPL-RT9479	\$ 32,116	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT9681	\$ 53,152	C	RENPL-RT9681	\$ 36,831	C	HENPL-RT9681	\$ 33,173	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT10070	\$ 55,761	C	RENPL-RT10070	\$ 39,336	C	HENPL-RT10070	\$ 35,678	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT10494	\$ 56,603	C	RENPL-RT10494	\$ 40,145	C	HENPL-RT10494	\$ 36,487	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT10519	\$ 54,439	C	RENPL-RT10519	\$ 38,067	C	HENPL-RT10519	\$ 34,408	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT8202	\$ 55,114	C	RENPL-RT8202	\$ 39,018	C	HENPL-RT8202	\$ 35,360	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT8330	\$ 56,205	C	RENPL-RT8330	\$ 39,763	C	HENPL-RT8330	\$ 36,105	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT9679	\$ 55,585	C	RENPL-RT9679	\$ 39,168	C	HENPL-RT9679	\$ 35,510	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT8648	\$ 49,644	C	RENPL-RT8648	\$ 33,470	C	HENPL-RT8648	\$ 29,812	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT8895	\$ 49,668	C	RENPL-RT8895	\$ 33,493	C	HENPL-RT8895	\$ 29,835	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT8960	\$ 49,963	C	RENPL-RT8960	\$ 33,776	C	HENPL-RT8960	\$ 30,118	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT9625	\$ 49,270	C	RENPL-RT9625	\$ 33,110	C	HENPL-RT9625	\$ 29,452	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT9904	\$ 48,745	C	RENPL-RT9904	\$ 32,606	C	HENPL-RT9904	\$ 28,948	C	\$ 14,900
IO-360-B1E	YES	ENPL-RT8593	\$ 49,023	C	RENPL-RT8593	\$ 32,873	C	HENPL-RT8593	\$ 29,215	C	\$ 14,900
IO-360-B1E	YES	ENPL-RT8709	\$ 48,950	C	RENPL-RT8709	\$ 32,804	C	HENPL-RT8709	\$ 29,145	C	\$ 14,900
IO-360-B1E	YES	ENPL-RT9747	\$ 49,183	C	RENPL-RT9747	\$ 33,027	C	HENPL-RT9747	\$ 29,368	C	\$ 14,900
IO-360-B1F	YES	ENPL-RT8434	\$ 49,668	C	RENPL-RT8434	\$ 33,493	C	HENPL-RT8434	\$ 29,834	C	\$ 14,900
IO-360-B1F6	YES	ENPL-RT8993	\$ 51,507	C	RENPL-RT8993	\$ 35,259	C	HENPL-RT8993	\$ 31,601	C	\$ 14,900
IO-360-B1G6	YES	ENPL-RT10304	\$ 51,486	C	RENPL-RT10304	\$ 35,239	C	HENPL-RT10304	\$ 31,580	C	\$ 14,900
IO-360-B1G6	YES	ENPL-RT9547	\$ 53,648	C	RENPL-RT9547	\$ 36,314	C	HENPL-RT9547	\$ 32,655	C	\$ 14,900
IO-360-B1G6	YES	ENPL-RT9760	\$ 51,534	C	RENPL-RT9760	\$ 35,286	C	HENPL-RT9760	\$ 31,627	C	\$ 14,900
IO-360-C1B	YES	ENPL-RT8667	\$ 52,598	C	RENPL-RT8667	\$ 36,307	C	HENPL-RT8667	\$ 32,649	C	\$ 14,900
IO-360-C1C	YES	ENPL-RT8612	\$ 50,481	C	RENPL-RT8612	\$ 34,273	C	HENPL-RT8612	\$ 30,615	A	\$ 14,900
IO-360-C1C	YES	ENPL-RT9632	\$ 50,703	C	RENPL-RT9632	\$ 34,487	C	HENPL-RT9632	\$ 30,828	B	\$ 14,900
IO-360-C1C	YES	ENPL-RT9907	\$ 51,323	C	RENPL-RT9907	\$ 35,083	C	HENPL-RT9907	\$ 31,425	B	\$ 14,900
IO-360-C1C *	YES	ENPL-RT10019	\$ 50,228	C	RENPL-RT10019	\$ 34,031	C	HENPL-RT10019	\$ 30,372	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT10214	\$ 53,474	C	RENPL-RT10214	\$ 37,149	C	HENPL-RT10214	\$ 33,490	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT10246	\$ 53,621	C	RENPL-RT10246	\$ 37,290	C	HENPL-RT10246	\$ 33,631	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT10540	\$ 53,221	C	RENPL-RT10540	\$ 36,555	C	HENPL-RT10540	\$ 32,896	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT8567	\$ 52,304	C	RENPL-RT8567	\$ 36,305	C	HENPL-RT8567	\$ 32,647	A	\$ 14,900
IO-360-C1C6	YES	ENPL-RT8879	\$ 53,738	C	RENPL-RT8879	\$ 37,403	C	HENPL-RT8879	\$ 33,744	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT9325	\$ 53,267	C	RENPL-RT9325	\$ 36,950	C	HENPL-RT9325	\$ 33,292	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT9593	\$ 52,508	C	RENPL-RT9593	\$ 36,221	C	HENPL-RT9593	\$ 32,562	B	\$ 14,900
IO-360-C1D6	YES	ENPL-RT10493	\$ 54,196	C	RENPL-RT10493	\$ 37,809	C	HENPL-RT10493	\$ 34,151	C	\$ 14,900
IO-360-C1D6	YES	ENPL-RT9353	\$ 53,665	C	RENPL-RT9353	\$ 37,332	C	HENPL-RT9353	\$ 33,674	C	\$ 14,900

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
IO-360-C1D6****	YES	ENPL-RT10317	\$ 53,841	C	RENPL-RT10317	\$ 37,501	C	HENPL-RT10317	\$ 33,842	C	\$ 14,900
IO-360-C1E6	YES	ENPL-RT8594	\$ 52,874	C	RENPL-RT8594	\$ 36,572	C	HENPL-RT8594	\$ 32,914	C	\$ 14,900
IO-360-C1F	YES	ENPL-RT9545	\$ 53,653	C	RENPL-RT9545	\$ 37,321	C	HENPL-RT9545	\$ 33,662	C	\$ 14,900
IO-360-C1G6	YES	ENPL-RT9693	\$ 56,622	C	RENPL-RT9693	\$ 40,173	C	HENPL-RT9693	\$ 36,514	C	\$ 14,900
IO-360-L2A	YES	ENPL-RT10185	\$ 50,159	C	RENPL-RT10185	\$ 33,999	C	HENPL-RT10185	\$ 30,340	B	\$ 14,900
IO-360-L2A	YES	ENPL-RT10230	\$ 49,425	C	RENPL-RT10230	\$ 33,295	C	HENPL-RT10230	\$ 29,636	A	\$ 14,900
IO-360-L2A	YES	ENPL-RT10294	\$ 50,796	C	RENPL-RT10294	\$ 33,689	C	HENPL-RT10294	\$ 30,031	B	\$ 14,900
IO-360-L2A	YES	ENPL-RT10437	\$ 49,607	C	RENPL-RT10437	\$ 33,470	C	HENPL-RT10437	\$ 29,811	B	\$ 14,900
IO-360-L2A	YES	ENPL-RT9543	\$ 49,890	C	RENPL-RT9543	\$ 33,741	C	HENPL-RT9543	\$ 30,082	A	\$ 14,900
IO-360-L2A	YES	ENPL-RT9918	\$ 49,847	C	RENPL-RT9918	\$ 34,248	C	HENPL-RT9918	\$ 30,589	B	\$ 14,900
IO-360-L2A	YES	ENPL-RT10596	\$ 48,748	C	RENPL-RT10596	\$ 32,835	C	HENPL-RT10596	\$ 29,177	B	\$ 14,900
IO-360-M1A	YES	ENPL-RT10051	\$ 48,850	C	RENPL-RT10051	\$ 32,708	C	HENPL-RT10051	\$ 29,049	C	\$ 14,900
IO-360-M1A	YES	ENPL-RT10623	\$ 48,973	C	RENPL-RT10623	\$ 32,825	C	HENPL-RT10623	\$ 29,166	C	\$ 14,900
IO-360-M1B	YES	ENPL-RT10117	\$ 47,767	C	RENPL-RT10117	\$ 31,667	C	HENPL-RT10117	\$ 28,009	C	\$ 14,900
IO-360-M1B	YES	ENPL-RT10167	\$ 48,400	C	RENPL-RT10167	\$ 32,275	C	HENPL-RT10167	\$ 28,616	C	\$ 14,900
LIO-360-C1E6	YES	ENPL-RT8598	\$ 53,746	C	RENPL-RT8598	\$ 37,410	C	HENPL-RT8598	\$ 33,752	C	\$ 14,900
LIO-360-M1A	YES	ENPL-RT10591	\$ 50,079	C	RENPL-RT10591	\$ 33,881	C	HENPL-RT10591	\$ 30,222	C	\$ 14,900
LO-360-A1G6D	YES	ENPL-RT8552	\$ 47,943	C	RENPL-RT8552	\$ 33,274	C	HENPL-RT8552	\$ 29,615	C	\$ 13,900
LO-360-A1G6D	YES	ENPL-RT8672	\$ 47,946	C	RENPL-RT8672	\$ 33,277	C	HENPL-RT8672	\$ 29,618	C	\$ 13,900
LO-360-A1H6	YES	ENPL-RT10570	\$ 45,923	C	RENPL-RT10570	\$ 31,333	C	HENPL-RT10570	\$ 27,675	A	\$ 13,900
LO-360-A1H6	YES	ENPL-RT8496	\$ 46,245	C	RENPL-RT8496	\$ 31,643	C	HENPL-RT8496	\$ 27,984	A	\$ 13,900
LO-360-A1H6	YES	ENPL-RT10679	\$ 46,329	C	RENPL-RT10679	\$ 31,724	C	HENPL-RT10679	\$ 28,065	A	\$ 13,900
LO-360-E1A6D	N/A	ENPL-10054	\$ 48,789	C	RENPL-10054	\$ 34,087	C	HENPL-10054	\$ 30,428	B	\$ 13,900
LO-360-E1A6D**	N/A	ENPL-10223	\$ 47,779	C	RENPL-10223	\$ 33,653	C	HENPL-10223	\$ 29,995	B	\$ 13,900
LO-360-E1A6D	N/A	ENPL-6719	\$ 48,239	C	RENPL-6719	\$ 33,559	C	HENPL-6719	\$ 29,900	A	\$ 13,900
LTO-360-E1A6D	N/A	ENPL-6948	\$ 69,781	D	RENPL-6948	\$ 52,072	D	HENPL-6948	\$ 46,584	D	\$ 17,000
O-360-A1A	YES	ENPL-RT10101	\$ 42,946	C	RENPL-RT10101	\$ 28,475	C	HENPL-RT10101	\$ 24,816	C	\$ 13,900
O-360-A1A	YES	ENPL-RT10183	\$ 42,633	C	RENPL-RT10183	\$ 28,174	C	HENPL-RT10183	\$ 24,516	C	\$ 13,900
O-360-A1A	YES	ENPL-RT10286	\$ 42,888	C	RENPL-RT10286	\$ 28,419	C	HENPL-RT10286	\$ 24,760	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8435	\$ 43,354	C	RENPL-RT8435	\$ 28,866	C	HENPL-RT8435	\$ 25,207	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8597	\$ 42,941	C	RENPL-RT8597	\$ 28,469	C	HENPL-RT8597	\$ 24,811	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8681	\$ 43,531	C	RENPL-RT8681	\$ 29,036	C	HENPL-RT8681	\$ 25,377	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8683	\$ 42,864	C	RENPL-RT8683	\$ 28,395	C	HENPL-RT8683	\$ 24,737	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8788	\$ 42,970	C	RENPL-RT8788	\$ 28,498	C	HENPL-RT8788	\$ 24,839	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8794	\$ 42,939	C	RENPL-RT8794	\$ 28,468	C	HENPL-RT8794	\$ 24,809	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8820	\$ 43,518	C	RENPL-RT8820	\$ 29,024	C	HENPL-RT8820	\$ 25,365	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8906	\$ 43,483	C	RENPL-RT8906	\$ 28,990	C	HENPL-RT8906	\$ 25,332	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8913	\$ 43,504	C	RENPL-RT8913	\$ 29,010	C	HENPL-RT8913	\$ 25,351	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8932	\$ 42,998	C	RENPL-RT8932	\$ 28,525	C	HENPL-RT8932	\$ 24,866	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9347	\$ 43,498	C	RENPL-RT9347	\$ 29,005	C	HENPL-RT9347	\$ 25,347	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9507	\$ 42,941	C	RENPL-RT9507	\$ 28,469	C	HENPL-RT9507	\$ 24,811	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9657	\$ 42,941	C	RENPL-RT9657	\$ 28,445	C	HENPL-RT9657	\$ 24,787	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9689	\$ 43,012	C	RENPL-RT9689	\$ 28,538	C	HENPL-RT9689	\$ 24,880	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9778	\$ 43,683	C	RENPL-RT9778	\$ 29,182	C	HENPL-RT9778	\$ 25,524	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9799	\$ 43,502	C	RENPL-RT9799	\$ 29,009	C	HENPL-RT9799	\$ 25,350	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9807	\$ 43,679	C	RENPL-RT9807	\$ 29,179	C	HENPL-RT9807	\$ 25,520	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9808	\$ 41,942	C	RENPL-RT9808	\$ 27,510	C	HENPL-RT9808	\$ 23,852	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9969	\$ 42,939	C	RENPL-RT9969	\$ 28,468	C	HENPL-RT9969	\$ 24,809	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8984	\$ 42,998	C	RENPL-RT8984	\$ 28,524	C	HENPL-RT8984	\$ 24,866	C	\$ 13,900
O-360-A1AD	YES	ENPL-RT10245	\$ 45,909	C	RENPL-RT10245	\$ 31,321	C	HENPL-RT10245	\$ 27,662	C	\$ 13,900
O-360-A1AD	YES	ENPL-RT10581	\$ 45,923	C	RENPL-RT10581	\$ 31,334	C	HENPL-RT10581	\$ 27,675	C	\$ 13,900
O-360-A1AD	YES	ENPL-RT8089	\$ 46,285	C	RENPL-RT8089	\$ 31,251	C	HENPL-RT8089	\$ 27,593	C	\$ 13,900
O-360-A1AD	YES	ENPL-RT8494	\$ 45,409	C	RENPL-RT8494	\$ 31,075	C	HENPL-RT8494	\$ 27,417	C	\$ 13,900
O-360-A1AD	YES	ENPL-RT10660	\$ 45,924	C	RENPL-RT10660	\$ 31,334	C	HENPL-RT10660	\$ 27,676	C	\$ 13,900
O-360-A1D	YES	ENPL-RT10080	\$ 42,877	C	RENPL-RT10080	\$ 28,408	C	HENPL-RT10080	\$ 24,750	C	\$ 13,900

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
O-360-A1D	YES	ENPL-RT10085	\$ 42,876	C	RENPL-RT10085	\$ 28,407	C	HENPL-RT10085	\$ 24,748	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8041	\$ 43,362	C	RENPL-RT8041	\$ 28,849	C	HENPL-RT8041	\$ 25,191	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8042	\$ 43,515	C	RENPL-RT8042	\$ 28,997	C	HENPL-RT8042	\$ 25,338	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8313	\$ 43,399	C	RENPL-RT8313	\$ 29,128	C	HENPL-RT8313	\$ 25,470	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8939	\$ 42,841	C	RENPL-RT8939	\$ 28,373	C	HENPL-RT8939	\$ 24,715	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8974	\$ 44,071	C	RENPL-RT8974	\$ 29,555	C	HENPL-RT8974	\$ 25,897	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9527	\$ 42,863	C	RENPL-RT9527	\$ 28,395	C	HENPL-RT9527	\$ 24,736	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9582	\$ 44,220	C	RENPL-RT9582	\$ 29,698	C	HENPL-RT9582	\$ 26,039	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9627	\$ 43,807	C	RENPL-RT9627	\$ 29,302	C	HENPL-RT9627	\$ 25,643	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9697	\$ 44,220	C	RENPL-RT9697	\$ 29,698	C	HENPL-RT9697	\$ 26,039	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9779	\$ 44,216	C	RENPL-RT9779	\$ 29,694	C	HENPL-RT9779	\$ 26,036	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9798	\$ 43,466	C	RENPL-RT9798	\$ 28,974	C	HENPL-RT9798	\$ 25,315	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9865	\$ 43,552	C	RENPL-RT9865	\$ 29,056	C	HENPL-RT9865	\$ 25,398	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT10501	\$ 44,840	C	RENPL-RT10501	\$ 30,294	C	HENPL-RT10501	\$ 26,635	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT9356	\$ 44,290	C	RENPL-RT9356	\$ 29,765	C	HENPL-RT9356	\$ 26,107	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT9666	\$ 44,442	C	RENPL-RT9666	\$ 29,911	C	HENPL-RT9666	\$ 26,253	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT9316	\$ 44,521	C	RENPL-RT9316	\$ 29,964	C	HENPL-RT9316	\$ 26,305	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT9529	\$ 44,694	C	RENPL-RT9529	\$ 30,081	C	HENPL-RT9529	\$ 26,423	C	\$ 13,900
O-360-A1F6D	YES	ENPL-RT5654	\$ 46,751	C	RENPL-RT5654	\$ 32,129	C	HENPL-RT5654	\$ 28,471	C	\$ 13,900
O-360-A1F6D	YES	ENPL-RT8105	\$ 46,667	C	RENPL-RT8105	\$ 32,049	C	HENPL-RT8105	\$ 28,390	C	\$ 13,900
O-360-A1G6D	YES	ENPL-RT8045	\$ 47,011	C	RENPL-RT8045	\$ 32,379	C	HENPL-RT8045	\$ 28,721	C	\$ 13,900
O-360-A1G6D	YES	ENPL-RT8671	\$ 47,009	C	RENPL-RT8671	\$ 32,377	C	HENPL-RT8671	\$ 28,718	C	\$ 13,900
O-360-A1G6D	YES	ENPL-RT10661	\$ 47,509	C	RENPL-RT10661	\$ 32,857	C	HENPL-RT10661	\$ 29,198	C	\$ 13,900
O-360-A1H6	YES	ENPL-RT10569	\$ 44,788	C	RENPL-RT10569	\$ 30,243	C	HENPL-RT10569	\$ 26,584	A	\$ 13,900
O-360-A1H6	YES	ENPL-RT8495	\$ 45,108	C	RENPL-RT8495	\$ 30,551	C	HENPL-RT8495	\$ 26,893	A	\$ 13,900
O-360-A1H6	YES	ENPL-RT10678	\$ 45,193	C	RENPL-RT10678	\$ 30,632	C	HENPL-RT10678	\$ 26,974	A	\$ 13,900
O-360-A1LD	YES	ENPL-RT9618	\$ 44,974	C	RENPL-RT9618	\$ 30,422	C	HENPL-RT9618	\$ 26,763	C	\$ 13,900
O-360-A1P	YES	ENPL-RT9334	\$ 43,104	C	RENPL-RT9334	\$ 28,626	C	HENPL-RT9334	\$ 24,967	C	\$ 13,900
O-360-A1P	YES	ENPL-RT9437	\$ 43,758	C	RENPL-RT9437	\$ 29,254	C	HENPL-RT9437	\$ 25,596	C	\$ 13,900
O-360-A1P	YES	ENPL-RT9940	\$ 43,255	C	RENPL-RT9940	\$ 28,772	C	HENPL-RT9940	\$ 25,113	C	\$ 13,900
O-360-A2A	YES	ENPL-RT8536	\$ 44,206	C	RENPL-RT8536	\$ 29,685	C	HENPL-RT8536	\$ 26,026	C	\$ 13,900
O-360-A2A	YES	ENPL-RT8613	\$ 43,763	C	RENPL-RT8613	\$ 29,259	C	HENPL-RT8613	\$ 25,601	C	\$ 13,900
O-360-A2A	YES	ENPL-RT8674	\$ 42,651	C	RENPL-RT8674	\$ 28,191	C	HENPL-RT8674	\$ 24,532	C	\$ 13,900
O-360-A2F	YES	ENPL-RT9378	\$ 43,067	C	RENPL-RT9378	\$ 28,591	C	HENPL-RT9378	\$ 24,932	C	\$ 13,900
O-360-A2F	YES	ENPL-RT9996	\$ 43,094	C	RENPL-RT9996	\$ 28,616	C	HENPL-RT9996	\$ 24,958	C	\$ 13,900
O-360-A2G	YES	ENPL-RT8575	\$ 43,456	C	RENPL-RT8575	\$ 28,965	C	HENPL-RT8575	\$ 25,306	C	\$ 13,900
O-360-A3A	YES	ENPL-RT10159	\$ 43,719	C	RENPL-RT10159	\$ 29,217	C	HENPL-RT10159	\$ 25,559	C	\$ 13,900
O-360-A3A	YES	ENPL-RT10527	\$ 42,873	C	RENPL-RT10527	\$ 28,736	C	HENPL-RT10527	\$ 25,078	C	\$ 13,900
O-360-A3A	YES	ENPL-RT8599	\$ 42,651	C	RENPL-RT8599	\$ 28,285	C	HENPL-RT8599	\$ 24,627	C	\$ 13,900
O-360-A3A	YES	ENPL-RT8614	\$ 43,256	C	RENPL-RT8614	\$ 28,772	C	HENPL-RT8614	\$ 25,114	C	\$ 13,900
O-360-A3A	YES	ENPL-RT8734	\$ 42,475	C	RENPL-RT8734	\$ 28,466	C	HENPL-RT8734	\$ 24,808	C	\$ 13,900
O-360-A3A	YES	ENPL-RT8771	\$ 43,298	C	RENPL-RT8771	\$ 28,813	C	HENPL-RT8771	\$ 25,154	C	\$ 13,900
O-360-A3A*	YES	ENPL-RT9633	\$ 42,860	C	RENPL-RT9633	\$ 28,936	C	HENPL-RT9633	\$ 25,278	C	\$ 13,900
O-360-A3A	YES	ENPL-RT9656	\$ 42,799	C	RENPL-RT9656	\$ 28,333	C	HENPL-RT9656	\$ 24,675	C	\$ 13,900
O-360-A3A	YES	ENPL-RT9838	\$ 43,283	C	RENPL-RT9838	\$ 28,798	C	HENPL-RT9838	\$ 25,139	C	\$ 13,900
O-360-A3A *	YES	ENPL-RT10357	\$ 42,930	C	RENPL-RT10357	\$ 28,459	C	HENPL-RT10357	\$ 24,801	C	\$ 13,900
O-360-A3AD	YES	ENPL-RT8660	\$ 44,800	C	RENPL-RT8660	\$ 30,255	C	HENPL-RT8660	\$ 26,597	C	\$ 13,900
O-360-A4A	YES	ENPL-RT8601	\$ 42,142	C	RENPL-RT8601	\$ 27,702	C	HENPL-RT8601	\$ 24,044	C	\$ 13,900
O-360-A4A	YES	ENPL-RT9652	\$ 42,889	C	RENPL-RT9652	\$ 28,420	C	HENPL-RT9652	\$ 24,761	C	\$ 13,900
O-360-A4A	YES	ENPL-RT9869	\$ 43,048	C	RENPL-RT9869	\$ 28,572	C	HENPL-RT9869	\$ 24,914	C	\$ 13,900
O-360-A4G	YES	ENPL-RT9361	\$ 42,988	C	RENPL-RT9361	\$ 28,515	C	HENPL-RT9361	\$ 24,857	C	\$ 13,900
O-360-A4J	YES	ENPL-RT10056	\$ 42,454	C	RENPL-RT10056	\$ 28,002	C	HENPL-RT10056	\$ 24,344	C	\$ 13,900
O-360-A4J	YES	ENPL-RT9340	\$ 42,887	C	RENPL-RT9340	\$ 28,417	C	HENPL-RT9340	\$ 24,759	C	\$ 13,900
O-360-A4K	YES	ENPL-RT10196	\$ 44,629	C	RENPL-RT10196	\$ 30,091	C	HENPL-RT10196	\$ 26,433	C	\$ 13,900
O-360-A4K	YES	ENPL-RT8053	\$ 42,896	C	RENPL-RT8053	\$ 28,426	C	HENPL-RT8053	\$ 24,767	C	\$ 13,900

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
O-360-A4K	YES	ENPL-RT8054	\$ 42,785	C	RENPL-RT8054	\$ 28,320	C	HENPL-RT8054	\$ 24,661	C	\$ 13,900
O-360-A4K	YES	ENPL-RT8056	\$ 42,875	C	RENPL-RT8056	\$ 28,406	C	HENPL-RT8056	\$ 24,748	C	\$ 13,900
O-360-A4K	YES	ENPL-RT8845	\$ 43,334	C	RENPL-RT8845	\$ 28,847	C	HENPL-RT8845	\$ 25,188	C	\$ 13,900
O-360-A4K	YES	ENPL-RT9648	\$ 42,934	C	RENPL-RT9648	\$ 28,463	C	HENPL-RT9648	\$ 24,805	C	\$ 13,900
O-360-A4K	YES	ENPL-RT9658	\$ 42,876	C	RENPL-RT9658	\$ 28,407	C	HENPL-RT9658	\$ 24,749	C	\$ 13,900
O-360-A4K	YES	ENPL-RT9871	\$ 42,506	C	RENPL-RT9871	\$ 28,052	C	HENPL-RT9871	\$ 24,394	C	\$ 13,900
O-360-A4K	YES	ENPL-RT9989	\$ 43,612	C	RENPL-RT9989	\$ 29,114	C	HENPL-RT9989	\$ 25,456	C	\$ 13,900
O-360-A4M	YES	ENPL-RT10672	\$ 43,244	C	RENPL-RT10672	\$ 28,761	C	HENPL-RT10672	\$ 25,102	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10004	\$ 43,322	C	RENPL-RT10004	\$ 28,836	C	HENPL-RT10004	\$ 25,177	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10052	\$ 42,717	C	RENPL-RT10052	\$ 28,255	C	HENPL-RT10052	\$ 24,596	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10250	\$ 42,968	C	RENPL-RT10250	\$ 28,496	C	HENPL-RT10250	\$ 24,837	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10326	\$ 43,789	C	RENPL-RT10326	\$ 29,285	C	HENPL-RT10326	\$ 25,626	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10335	\$ 43,498	C	RENPL-RT10335	\$ 28,981	C	HENPL-RT10335	\$ 25,322	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10465	\$ 43,789	C	RENPL-RT10465	\$ 29,285	C	HENPL-RT10465	\$ 25,626	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10516	\$ 42,383	C	RENPL-RT10516	\$ 27,934	C	HENPL-RT10516	\$ 24,275	B	\$ 13,900
O-360-A4M	YES	ENPL-RT8057	\$ 42,383	C	RENPL-RT8057	\$ 27,934	C	HENPL-RT8057	\$ 24,275	A	\$ 13,900
O-360-A4M	YES	ENPL-RT8863	\$ 41,896	C	RENPL-RT8863	\$ 27,466	C	HENPL-RT8863	\$ 23,808	A	\$ 13,900
O-360-A4M	YES	ENPL-RT8883	\$ 42,099	C	RENPL-RT8883	\$ 27,868	C	HENPL-RT8883	\$ 24,210	B	\$ 13,900
O-360-A4M	YES	ENPL-RT8884	\$ 43,103	C	RENPL-RT8884	\$ 28,625	C	HENPL-RT8884	\$ 24,967	B	\$ 13,900
O-360-A4M	YES	ENPL-RT8928	\$ 42,707	C	RENPL-RT8928	\$ 28,245	C	HENPL-RT8928	\$ 24,587	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9358	\$ 43,789	C	RENPL-RT9358	\$ 29,284	C	HENPL-RT9358	\$ 25,625	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9399	\$ 43,346	C	RENPL-RT9399	\$ 28,859	C	HENPL-RT9399	\$ 25,200	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9440	\$ 43,388	C	RENPL-RT9440	\$ 28,899	C	HENPL-RT9440	\$ 25,241	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9451	\$ 43,847	C	RENPL-RT9451	\$ 29,340	C	HENPL-RT9451	\$ 25,681	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9655	\$ 43,377	C	RENPL-RT9655	\$ 28,889	C	HENPL-RT9655	\$ 25,230	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9856	\$ 43,068	C	RENPL-RT9856	\$ 28,591	C	HENPL-RT9856	\$ 24,933	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9890	\$ 43,346	C	RENPL-RT9890	\$ 28,859	C	HENPL-RT9890	\$ 25,200	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9895	\$ 43,505	C	RENPL-RT9895	\$ 29,011	C	HENPL-RT9895	\$ 25,353	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10386	\$ 43,220	C	RENPL-RT10386	\$ 28,737	C	HENPL-RT10386	\$ 25,079	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10339	\$ 43,784	C	RENPL-RT10339	\$ 29,281	C	HENPL-RT10339	\$ 25,623	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10734	\$ 43,441	C	RENPL-RT10734	\$ 28,981	C	HENPL-RT10734	\$ 25,323	B	\$ 13,900
O-360-A4N	YES	ENPL-RT8165	\$ 43,417	C	RENPL-RT8165	\$ 28,927	C	HENPL-RT8165	\$ 25,269	C	\$ 13,900
O-360-A4P	YES	ENPL-RT8937	\$ 43,142	C	RENPL-RT8937	\$ 28,662	C	HENPL-RT8937	\$ 25,004	C	\$ 13,900
O-360-A5AD	N/A	ENPL-RT8226	\$ 41,593	C	RENPL-RT8226	\$ 27,175	C	HENPL-RT8226	\$ 23,516	C	\$ 13,900
O-360-C1E	YES	ENPL-RT8947	\$ 43,538	C	RENPL-RT8947	\$ 29,043	C	HENPL-RT8947	\$ 25,384	C	\$ 13,900
O-360-C1E	YES	ENPL-RT9797	\$ 43,667	C	RENPL-RT9797	\$ 29,167	C	HENPL-RT9797	\$ 25,509	C	\$ 13,900
O-360-C1F	YES	ENPL-RT8284	\$ 43,695	C	RENPL-RT8284	\$ 29,194	C	HENPL-RT8284	\$ 25,535	C	\$ 13,900
O-360-C1G	YES	ENPL-RT10043	\$ 43,323	C	RENPL-RT10043	\$ 28,837	C	HENPL-RT10043	\$ 25,178	C	\$ 13,900
O-360-C1G	YES	ENPL-RT8427	\$ 43,227	C	RENPL-RT8427	\$ 28,744	C	HENPL-RT8427	\$ 25,086	C	\$ 13,900
O-360-C1G	YES	ENPL-RT9499	\$ 43,748	C	RENPL-RT9499	\$ 29,243	C	HENPL-RT9499	\$ 25,585	C	\$ 13,900
O-360-C2A	YES	ENPL-RT8257	\$ 43,161	C	RENPL-RT8257	\$ 28,681	C	HENPL-RT8257	\$ 25,022	C	\$ 13,900
O-360-C2E	YES	ENPL-RT8262	\$ 43,375	C	RENPL-RT8262	\$ 28,887	C	HENPL-RT8262	\$ 25,228	C	\$ 13,900
O-360-C2E	YES	ENPL-RT9610	\$ 43,362	C	RENPL-RT9610	\$ 28,874	C	HENPL-RT9610	\$ 25,215	C	\$ 13,900
O-360-C2E	YES	ENPL-RT9745	\$ 43,525	C	RENPL-RT9745	\$ 29,031	C	HENPL-RT9745	\$ 25,372	C	\$ 13,900
O-360-C2E	YES	ENPL-RT9764	\$ 43,525	C	RENPL-RT9764	\$ 29,031	C	HENPL-RT9764	\$ 25,372	C	\$ 13,900
O-360-C2E	YES	ENPL-RT9824	\$ 43,505	C	RENPL-RT9824	\$ 29,011	C	HENPL-RT9824	\$ 25,353	C	\$ 13,900
O-360-C2E	YES	ENPL-RT9873	\$ 43,141	C	RENPL-RT9873	\$ 28,662	C	HENPL-RT9873	\$ 25,004	C	\$ 13,900
O-360-C4F	YES	ENPL-RT8986	\$ 43,554	C	RENPL-RT8986	\$ 29,059	C	HENPL-RT8986	\$ 25,400	C	\$ 13,900
O-360-C4P	YES	ENPL-RT10145	\$ 42,278	C	RENPL-RT10145	\$ 27,832	C	HENPL-RT10145	\$ 24,174	C	\$ 13,900
O-360-C4P	YES	ENPL-RT9394	\$ 42,539	C	RENPL-RT9394	\$ 28,083	C	HENPL-RT9394	\$ 24,425	C	\$ 13,900
O-360-E1A6D**	N/A	ENPL-10222	\$ 46,994	C	RENPL-10222	\$ 32,887	C	HENPL-10222	\$ 29,228	B	\$ 13,900
O-360-E1A6D	N/A	ENPL-6650	\$ 47,520	C	RENPL-6650	\$ 32,867	C	HENPL-6650	\$ 29,209	A	\$ 13,900
O-360-E1A6D	N/A	ENPL-9791	\$ 47,830	C	RENPL-9791	\$ 33,166	C	HENPL-9791	\$ 29,507	B	\$ 13,900
O-360-E1A6D	N/A	ENPL-9853	\$ 47,840	C	RENPL-9853	\$ 33,176	C	HENPL-9853	\$ 29,517	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT10504	\$ 44,509	C	RENPL-RT10504	\$ 29,976	C	HENPL-RT10504	\$ 26,317	B	\$ 13,900

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
		NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
ENGINE MODEL	ROLLER TAPPETS	PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
O-360-F1A6	YES	ENPL-RT10507	\$ 44,404	C	RENPL-RT10507	\$ 29,875	C	HENPL-RT10507	\$ 26,216	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT8166	\$ 44,509	C	RENPL-RT8166	\$ 29,976	C	HENPL-RT8166	\$ 26,317	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT8898	\$ 44,404	C	RENPL-RT8898	\$ 29,874	C	HENPL-RT8898	\$ 26,216	A	\$ 13,900
O-360-F1A6	YES	ENPL-RT9845	\$ 45,071	C	RENPL-RT9845	\$ 30,515	C	HENPL-RT9845	\$ 26,857	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT9903	\$ 45,135	C	RENPL-RT9903	\$ 30,577	C	HENPL-RT9903	\$ 26,918	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT9917	\$ 45,226	C	RENPL-RT9917	\$ 30,664	C	HENPL-RT9917	\$ 27,006	B	\$ 13,900
O-360-J2A	YES	ENPL-RT10155	\$ 42,551	C	RENPL-RT10155	\$ 29,011	C	HENPL-RT10155	\$ 25,352	C	\$ 13,900
O-360-J2A	YES	ENPL-RT10200	\$ 42,551	C	RENPL-RT10200	\$ 29,011	C	HENPL-RT10200	\$ 25,352	C	\$ 13,900
TIO-360-C1A6D	N/A	ENPL-8327	\$ 81,716	D	RENPL-8327	\$ 63,581	D	HENPL-8327	\$ 58,093	D	\$ 17,000
TIO-360-C1A6D	N/A	ENPL-9930	\$ 82,357	D	RENPL-9930	\$ 64,196	D	HENPL-9930	\$ 58,708	D	\$ 17,000
TO-360-C1A6D	N/A	ENPL-7322	\$ 73,093	D	RENPL-7322	\$ 55,298	D	HENPL-7322	\$ 49,810	D	\$ 17,000
TO-360-C1A6D	N/A	ENPL-9748	\$ 73,616	D	RENPL-9748	\$ 55,801	D	HENPL-9748	\$ 50,313	D	\$ 17,000
TO-360-E1A6D	N/A	ENPL-6947	\$ 68,547	D	RENPL-6947	\$ 50,931	D	HENPL-6947	\$ 45,444	D	\$ 17,000
IO-390-A1A6	YES	ENPL-RT10620	\$ 55,644	C	RENPL-RT10620	\$ 36,435	C	HENPL-RT10620	\$ 36,435	C	\$ 15,900
AEIO-540-D4A5	YES	ENPL-RT10144	\$ 70,136	C	RENPL-RT10144	\$ 50,202	C	HENPL-RT10144	\$ 45,933	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT10285	\$ 68,241	C	RENPL-RT10285	\$ 48,382	C	HENPL-RT10285	\$ 44,113	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT8318	\$ 69,630	C	RENPL-RT8318	\$ 49,716	C	HENPL-RT8318	\$ 45,447	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT8417	\$ 67,331	C	RENPL-RT8417	\$ 47,508	C	HENPL-RT8417	\$ 43,240	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT8515	\$ 67,851	C	RENPL-RT8515	\$ 48,007	C	HENPL-RT8515	\$ 43,738	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9339	\$ 69,121	C	RENPL-RT9339	\$ 49,227	C	HENPL-RT9339	\$ 44,958	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9406	\$ 68,797	C	RENPL-RT9406	\$ 48,916	C	HENPL-RT9406	\$ 44,648	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9442	\$ 67,971	C	RENPL-RT9442	\$ 48,122	C	HENPL-RT9442	\$ 43,854	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9445	\$ 70,136	C	RENPL-RT9445	\$ 50,202	C	HENPL-RT9445	\$ 45,933	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9783	\$ 68,382	C	RENPL-RT9783	\$ 48,517	C	HENPL-RT9783	\$ 44,249	C	\$ 17,600
AEIO-540-D4B5	YES	ENPL-RT8768	\$ 68,072	C	RENPL-RT8768	\$ 48,219	C	HENPL-RT8768	\$ 43,951	C	\$ 17,600
AEIO-540-D4B5	YES	ENPL-RT8836	\$ 66,596	C	RENPL-RT8836	\$ 46,802	C	HENPL-RT8836	\$ 42,533	C	\$ 17,600
AEIO-540-D4D5	YES	ENPL-RT9512	\$ 73,117	C	RENPL-RT9512	\$ 53,065	C	HENPL-RT9512	\$ 48,797	C	\$ 17,600
AEIO-540-L1B5	YES	ENPL-RT8544	\$ 73,714	C	RENPL-RT8544	\$ 50,557	C	HENPL-RT8544	\$ 46,289	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT9566	\$ 74,918	C	RENPL-RT9566	\$ 51,714	C	HENPL-RT9566	\$ 47,445	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT9609	\$ 73,097	C	RENPL-RT9609	\$ 49,965	C	HENPL-RT9609	\$ 45,696	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT9893	\$ 74,874	C	RENPL-RT9893	\$ 51,671	C	HENPL-RT9893	\$ 47,403	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT9899	\$ 74,957	C	RENPL-RT9899	\$ 51,751	C	HENPL-RT9899	\$ 47,483	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT8985	\$ 74,896	C	RENPL-RT8985	\$ 51,693	C	HENPL-RT8985	\$ 47,425	C	\$ 19,900
AEIO-540-L1B5D	YES	ENPL-RT7362	\$ 75,789	C	RENPL-RT7362	\$ 52,550	C	HENPL-RT7362	\$ 48,282	C	\$ 19,900
AEIO-540-L1B5D	YES	ENPL-RT7432	\$ 76,412	C	RENPL-RT7432	\$ 53,149	D	HENPL-RT7432	\$ 48,881	C	\$ 19,900
AEIO-540-L1B5D	YES	ENPL-RT7471	\$ 76,412	C	RENPL-RT7471	\$ 53,149	D	HENPL-RT7471	\$ 48,880	D	\$ 19,900
IO-540-AA1A5	YES	ENPL-RT10224	\$ 73,990	C	RENPL-RT10224	\$ 53,904	C	HENPL-RT10224	\$ 49,635	C	\$ 17,600
IO-540-AA1A5	YES	ENPL-RT8481	\$ 73,655	C	RENPL-RT8481	\$ 53,582	C	HENPL-RT8481	\$ 49,314	C	\$ 17,600
IO-540-AA1B5	YES	ENPL-RT8873	\$ 67,705	C	RENPL-RT8873	\$ 47,867	C	HENPL-RT8873	\$ 43,599	C	\$ 17,600
IO-540-AB1A5	YES	ENPL-RT10221	\$ 68,292	C	RENPL-RT10221	\$ 48,431	C	HENPL-RT10221	\$ 44,163	B	\$ 17,600
IO-540-AB1A5	YES	ENPL-RT10231	\$ 68,219	C	RENPL-RT10231	\$ 48,361	C	HENPL-RT10231	\$ 44,093	A	\$ 17,600
IO-540-AB1A5	YES	ENPL-RT9544	\$ 67,529	C	RENPL-RT9544	\$ 47,698	C	HENPL-RT9544	\$ 43,429	A	\$ 17,600
IO-540-AB1A5	YES	ENPL-RT10438	\$ 68,526	C	RENPL-RT10438	\$ 48,658	C	HENPL-RT10438	\$ 44,390	A	\$ 17,600
IO-540-AC1A5	YES	ENPL-RT10148	\$ 76,385	C	RENPL-RT10148	\$ 56,205	C	HENPL-RT10148	\$ 51,936	A	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10160	\$ 73,692	C	RENPL-RT10160	\$ 53,618	C	HENPL-RT10160	\$ 49,349	C	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10202	\$ 73,692	C	RENPL-RT10202	\$ 53,618	C	HENPL-RT10202	\$ 49,349	C	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10278	\$ 73,692	C	RENPL-RT10278	\$ 53,618	C	HENPL-RT10278	\$ 49,349	C	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10293	\$ 73,451	C	RENPL-RT10293	\$ 53,386	C	HENPL-RT10293	\$ 49,118	C	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10356	\$ 73,698	C	RENPL-RT10356	\$ 53,623	C	HENPL-RT10356	\$ 49,355	C	\$ 17,600
IO-540-C1B5	YES	ENPL-RT9954	\$ 63,807	C	RENPL-RT9954	\$ 44,123	C	HENPL-RT9954	\$ 39,855	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT10653	\$ 63,474	C	RENPL-RT10653	\$ 43,803	C	HENPL-RT10653	\$ 39,535	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT10523	\$ 63,369	C	RENPL-RT10523	\$ 43,702	C	HENPL-RT10523	\$ 39,434	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8303	\$ 63,831	C	RENPL-RT8303	\$ 44,146	C	HENPL-RT8303	\$ 39,878	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8390	\$ 63,958	C	RENPL-RT8390	\$ 44,268	C	HENPL-RT8390	\$ 40,000	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8458	\$ 63,958	C	RENPL-RT8458	\$ 44,268	C	HENPL-RT8458	\$ 39,999	B	\$ 17,600

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
IO-540-C4B5	YES	ENPL-RT8602	\$ 63,794	C	RENPL-RT8602	\$ 44,110	C	HENPL-RT8602	\$ 39,842	A	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8621	\$ 63,808	C	RENPL-RT8621	\$ 44,124	C	HENPL-RT8621	\$ 39,855	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8991	\$ 63,781	C	RENPL-RT8991	\$ 44,097	C	HENPL-RT8991	\$ 39,829	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9743	\$ 64,633	C	RENPL-RT9743	\$ 44,916	C	HENPL-RT9743	\$ 40,647	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9762	\$ 65,934	C	RENPL-RT9762	\$ 46,166	C	HENPL-RT9762	\$ 41,897	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9784	\$ 63,794	C	RENPL-RT9784	\$ 44,838	C	HENPL-RT9784	\$ 40,570	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9915	\$ 63,958	C	RENPL-RT9915	\$ 44,268	C	HENPL-RT9915	\$ 40,000	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9972	\$ 63,622	C	RENPL-RT9972	\$ 43,945	C	HENPL-RT9972	\$ 39,677	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT10099	\$ 63,194	C	RENPL-RT10099	\$ 43,534	C	HENPL-RT10099	\$ 39,266	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT10710	\$ 63,990	C	RENPL-RT10710	\$ 44,299	C	HENPL-RT10710	\$ 40,030	B	\$ 17,600
IO-540-C4D5	YES	ENPL-RT8724	\$ 64,354	C	RENPL-RT8724	\$ 44,648	C	HENPL-RT8724	\$ 40,380	C	\$ 17,600
IO-540-C4D5	YES	ENPL-RT8916	\$ 64,354	C	RENPL-RT8916	\$ 47,831	C	HENPL-RT9816	\$ 43,563	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT10692	\$ 65,637	C	RENPL-RT10692	\$ 46,639	C	HENPL-RT10692	\$ 42,371	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT10582	\$ 66,138	C	RENPL-RT10582	\$ 46,361	C	HENPL-RT10582	\$ 42,093	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT8274	\$ 65,637	C	RENPL-RT8274	\$ 45,880	C	HENPL-RT8274	\$ 41,612	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT8468	\$ 65,559	C	RENPL-RT8468	\$ 45,806	C	HENPL-RT8468	\$ 41,537	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT8542	\$ 65,623	C	RENPL-RT8542	\$ 45,867	C	HENPL-RT8542	\$ 41,599	C	\$ 17,600
IO-540-C4D5D*	YES	ENPL-RT10204	\$ 65,542	C	RENPL-RT10204	\$ 44,385	C	HENPL-RT10204	\$ 40,117	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT6926	\$ 63,443	C	RENPL-RT6926	\$ 43,773	C	HENPL-RT6926	\$ 39,505	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT8680	\$ 63,328	C	RENPL-RT8680	\$ 43,663	C	HENPL-RT8680	\$ 39,394	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT9781	\$ 63,424	C	RENPL-RT9781	\$ 43,755	C	HENPL-RT9781	\$ 39,487	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT9809	\$ 63,550	C	RENPL-RT9809	\$ 43,876	C	HENPL-RT9809	\$ 39,608	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT9942	\$ 63,572	C	RENPL-RT9942	\$ 43,897	C	HENPL-RT9942	\$ 39,629	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT9979	\$ 62,707	C	RENPL-RT9979	\$ 43,067	C	HENPL-RT9979	\$ 38,798	C	\$ 17,600
IO-540-D4B5	YES	ENPL-RT10394	\$ 64,685	C	RENPL-RT10394	\$ 44,966	C	HENPL-RT10394	\$ 40,698	C	\$ 17,600
IO-540-G1D5	YES	ENPL-RT10416	\$ 71,141	C	RENPL-RT10416	\$ 51,168	C	HENPL-RT10416	\$ 46,899	C	\$ 17,600
IO-540-J4A5	YES	ENPL-RT9816	\$ 67,668	C	RENPL-RT9816	\$ 47,831	C	HENPL-RT9816	\$ 43,563	C	\$ 17,600
IO-540-J4A5	YES	ENPL-RT9962	\$ 67,024	C	RENPL-RT9962	\$ 47,213	C	HENPL-RT9962	\$ 42,945	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT10595	\$ 70,272	C	RENPL-RT10595	\$ 50,332	C	HENPL-RT10595	\$ 46,064	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT8679	\$ 70,930	C	RENPL-RT8679	\$ 50,964	C	HENPL-RT8679	\$ 46,696	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT9755	\$ 70,921	C	RENPL-RT9755	\$ 50,956	C	HENPL-RT9755	\$ 46,688	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT9801	\$ 71,229	C	RENPL-RT9801	\$ 51,252	C	HENPL-RT9801	\$ 46,984	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT9862	\$ 70,755	C	RENPL-RT9862	\$ 50,796	C	HENPL-RT9862	\$ 46,528	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT10741	\$ 75,591	C	RENPL-RT10741	\$ 54,220	C	HENPL-RT10741	\$ 49,952	C	\$ 17,600
IO-540-K1A5D	YES	ENPL-RT8537	\$ 73,521	C	RENPL-RT8537	\$ 53,453	C	HENPL-RT8537	\$ 49,185	C	\$ 17,600
IO-540-K1A5D	YES	ENPL-RT9848	\$ 73,701	C	RENPL-RT9848	\$ 53,626	C	HENPL-RT9848	\$ 49,358	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT10234	\$ 71,735	C	RENPL-RT10234	\$ 51,738	C	HENPL-RT10234	\$ 47,470	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT10248	\$ 71,632	C	RENPL-RT10248	\$ 51,639	C	HENPL-RT10248	\$ 47,371	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT10538	\$ 72,139	C	RENPL-RT10538	\$ 52,126	C	HENPL-RT10538	\$ 47,858	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT8584	\$ 71,407	C	RENPL-RT8584	\$ 51,423	C	HENPL-RT8584	\$ 47,154	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT9419	\$ 71,503	C	RENPL-RT9419	\$ 51,514	C	HENPL-RT9419	\$ 47,246	C	\$ 17,600
IO-540-K1D5	YES	ENPL-RT8859	\$ 72,016	C	RENPL-RT8859	\$ 52,008	C	HENPL-RT8859	\$ 47,740	C	\$ 17,600
IO-540-K1E5	YES	ENPL-RT9371	\$ 71,861	C	RENPL-RT9371	\$ 51,859	C	HENPL-RT9371	\$ 47,591	C	\$ 17,600
IO-540-K1F5	YES	ENPL-RT10306	\$ 70,986	C	RENPL-RT10306	\$ 51,018	C	HENPL-RT10306	\$ 46,750	C	\$ 17,600
IO-540-K1F5	YES	ENPL-RT6625	\$ 72,743	C	RENPL-RT6625	\$ 52,706	C	HENPL-RT6625	\$ 48,438	C	\$ 17,600
IO-540-K1F5	YES	ENPL-RT9914	\$ 72,103	C	RENPL-RT9914	\$ 52,092	C	HENPL-RT9914	\$ 47,823	C	\$ 17,600
IO-540-K1G5	YES	ENPL-RT10025	\$ 68,956	C	RENPL-RT10025	\$ 49,069	C	HENPL-RT10025	\$ 44,801	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT10324	\$ 68,531	C	RENPL-RT10324	\$ 48,660	C	HENPL-RT10324	\$ 44,392	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT10397	\$ 69,032	C	RENPL-RT10397	\$ 49,141	C	HENPL-RT10397	\$ 44,873	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT8426	\$ 69,335	C	RENPL-RT8426	\$ 49,433	C	HENPL-RT8426	\$ 45,165	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT8581	\$ 68,751	C	RENPL-RT8581	\$ 48,872	C	HENPL-RT8581	\$ 44,604	A	\$ 17,600
IO-540-K1G5	YES	ENPL-RT8969	\$ 68,879	C	RENPL-RT8969	\$ 48,994	C	HENPL-RT8969	\$ 44,726	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT8972	\$ 68,574	C	RENPL-RT8972	\$ 48,702	C	HENPL-RT8972	\$ 44,433	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9386	\$ 68,669	C	RENPL-RT9386	\$ 48,793	C	HENPL-RT9386	\$ 44,525	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9591	\$ 71,090	C	RENPL-RT9591	\$ 51,119	C	HENPL-RT9591	\$ 46,850	B	\$ 17,600

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
		NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
ENGINE MODEL	ROLLER TAPPETS	PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
IO-540-K1G5	YES	ENPL-RT9629	\$ 68,885	C	RENPL-RT9629	\$ 49,001	C	HENPL-RT9629	\$ 44,732	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9691	\$ 68,565	C	RENPL-RT9691	\$ 48,693	C	HENPL-RT9691	\$ 44,425	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9788	\$ 68,721	C	RENPL-RT9788	\$ 48,843	C	HENPL-RT9788	\$ 44,574	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT10645	\$ 71,199	C	RENPL-RT10645	\$ 51,223	C	HENPL-RT10645	\$ 46,955	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9861	\$ 68,712	C	RENPL-RT9861	\$ 48,834	C	HENPL-RT9861	\$ 44,566	B	\$ 17,600
IO-540-K1G5D	YES	ENPL-RT10331	\$ 70,708	C	RENPL-RT10331	\$ 50,751	C	HENPL-RT10331	\$ 46,483	B	\$ 17,600
IO-540-K1G5D	YES	ENPL-RT8279	\$ 72,092	C	RENPL-RT8279	\$ 52,081	C	HENPL-RT8279	\$ 47,813	A	\$ 17,600
IO-540-K1G5D	YES	ENPL-RT8450	\$ 71,900	C	RENPL-RT8450	\$ 51,896	C	HENPL-RT8450	\$ 47,628	B	\$ 17,600
IO-540-K1G5D	YES	ENPL-RT9889	\$ 71,367	C	RENPL-RT9889	\$ 51,385	C	HENPL-RT9889	\$ 47,116	B	\$ 17,600
IO-540-K1H5	YES	ENPL-RT10114	\$ 71,090	C	RENPL-RT10114	\$ 51,119	C	HENPL-RT10114	\$ 46,851	B	\$ 17,600
IO-540-K1J5	YES	ENPL-RT8892	\$ 70,857	C	RENPL-RT8892	\$ 50,894	C	HENPL-RT8892	\$ 46,626	C	\$ 17,600
IO-540-K1J5	YES	ENPL-RT10229	\$ 70,843	C	RENPL-RT10229	\$ 50,881	C	HENPL-RT10229	\$ 46,613	C	\$ 17,600
IO-540-K1J5D	YES	ENPL-RT8346	\$ 71,664	C	RENPL-RT8346	\$ 51,669	C	HENPL-RT8346	\$ 47,401	C	\$ 17,600
IO-540-K1K5	YES	ENPL-RT8582	\$ 69,542	C	RENPL-RT8582	\$ 49,631	C	HENPL-RT8582	\$ 45,363	C	\$ 17,600
IO-540-L1C5	YES	ENPL-RT9800	\$ 72,107	C	RENPL-RT9800	\$ 52,095	C	HENPL-RT9800	\$ 47,827	C	\$ 17,600
IO-540-M1A5	YES	ENPL-RT8658	\$ 71,267	C	RENPL-RT8658	\$ 51,288	C	HENPL-RT8658	\$ 47,020	C	\$ 17,600
IO-540-M1A5	YES	ENPL-RT9343	\$ 72,145	C	RENPL-RT9343	\$ 52,132	C	HENPL-RT9343	\$ 47,863	C	\$ 17,600
IO-540-M1B5D	YES	ENPL-RT7027	\$ 74,193	C	RENPL-RT7027	\$ 54,099	C	HENPL-RT7027	\$ 49,831	C	\$ 17,600
IO-540-M1C5	YES	ENPL-RT10344	\$ 74,260	C	RENPL-RT10344	\$ 53,374	C	HENPL-RT10344	\$ 49,106	C	\$ 17,600
IO-540-M1C5	YES	ENPL-RT8935	\$ 73,690	C	RENPL-RT8935	\$ 52,827	C	HENPL-RT8935	\$ 48,559	C	\$ 17,600
IO-540-N1A5	YES	ENPL-RT8914	\$ 68,919	C	RENPL-RT8914	\$ 49,033	C	HENPL-RT8914	\$ 44,765	C	\$ 17,600
IO-540-R1A5	YES	ENPL-RT9988	\$ 71,000	C	RENPL-RT9988	\$ 51,032	C	HENPL-RT9988	\$ 46,764	C	\$ 17,600
IO-540-S1A5	YES	ENPL-RT8554	\$ 73,383	C	RENPL-RT8554	\$ 53,320	C	HENPL-RT8554	\$ 49,052	C	\$ 17,600
IO-540-T4A5D	YES	ENPL-RT5243	\$ 69,923	C	RENPL-RT5243	\$ 49,997	C	HENPL-RT5243	\$ 45,729	C	\$ 17,600
IO-540-T4B5	YES	ENPL-RT8865	\$ 64,485	C	RENPL-RT8865	\$ 44,774	C	HENPL-RT8865	\$ 40,506	C	\$ 17,600
IO-540-T4B5	YES	ENPL-RT9641	\$ 64,351	C	RENPL-RT9641	\$ 44,645	C	HENPL-RT9641	\$ 40,377	C	\$ 17,600
IO-540-T4B5	YES	ENPL-RT9766	\$ 64,880	C	RENPL-RT9766	\$ 45,153	C	HENPL-RT9766	\$ 40,885	C	\$ 17,600
IO-540-T4B5	YES	ENPL-RT9785	\$ 64,880	C	RENPL-RT9785	\$ 45,153	C	HENPL-RT9785	\$ 40,885	C	\$ 17,600
IO-540-T4B5	YES	ENPL-RT9950	\$ 64,487	C	RENPL-RT9950	\$ 44,776	C	HENPL-RT9950	\$ 40,507	C	\$ 17,600
IO-540-T4B5D	YES	ENPL-RT8838	\$ 66,693	C	RENPL-RT8838	\$ 46,894	C	HENPL-RT8838	\$ 42,626	C	\$ 17,600
IO-540-V4A5	YES	ENPL-RT10227	\$ 64,822	C	RENPL-RT10227	\$ 45,098	C	HENPL-RT10227	\$ 40,830	C	\$ 17,600
IO-540-V4A5	YES	ENPL-RT10410	\$ 67,511	C	RENPL-RT10410	\$ 47,681	C	HENPL-RT10410	\$ 43,413	C	\$ 17,600
IO-540-V4A5	YES	ENPL-RT9551	\$ 67,212	C	RENPL-RT9551	\$ 47,393	C	HENPL-RT9551	\$ 43,125	C	\$ 17,600
IO-540-V4A5	YES	ENPL-RT9570	\$ 65,385	C	RENPL-RT9570	\$ 45,639	C	HENPL-RT9570	\$ 41,370	C	\$ 17,600
IO-540-W1A5	YES	ENPL-RT9493	\$ 62,596	D	RENPL-RT9493	\$ 42,960	D	HENPL-RT9493	\$ 38,692	D	\$ 17,600
IO-540-W1A5	YES	ENPL-RT9494	\$ 62,710	D	RENPL-RT9494	\$ 43,069	D	HENPL-RT9494	\$ 38,800	D	\$ 17,600
IO-540-W1A5D	YES	ENPL-RT7209	\$ 66,160	D	RENPL-RT7209	\$ 46,383	D	HENPL-RT7209	\$ 42,115	D	\$ 17,600
LTIO-540-F2BD	N/A	ENPL-8200	\$ 94,020	C	RENPL-8200	\$ 69,426	C	HENPL-8200	\$ 63,328	C	\$ 22,000
LTIO-540-J2B	N/A	ENPL-10291	\$ 91,599	C	RENPL-10291	\$ 67,153	C	HENPL-10291	\$ 61,055	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-10297	\$ 91,599	C	RENPL-10297	\$ 67,153	C	HENPL-10297	\$ 61,055	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-10383	\$ 91,950	C	RENPL-10383	\$ 67,490	C	HENPL-10383	\$ 61,392	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-8122	\$ 91,601	C	RENPL-8122	\$ 67,154	C	HENPL-8122	\$ 61,056	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-8946	\$ 91,599	C	RENPL-8946	\$ 67,153	C	HENPL-8946	\$ 61,055	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-9402	\$ 91,601	C	RENPL-9402	\$ 67,154	C	HENPL-9402	\$ 61,056	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-10302	\$ 92,363	C	RENPL-10302	\$ 67,886	C	HENPL-10302	\$ 61,788	B	\$ 22,000
LTIO-540-J2BD	N/A	ENPL-8148	\$ 92,212	C	RENPL-8148	\$ 67,670	C	HENPL-8148	\$ 61,573	A	\$ 22,000
LTIO-540-J2BD	N/A	ENPL-9790	\$ 91,968	C	RENPL-9790	\$ 67,506	C	HENPL-9790	\$ 61,408	B	\$ 22,000
LTIO-540-U2A	N/A	ENPL-8650	\$ 100,026	C	RENPL-8650	\$ 64,973	C	HENPL-8650	\$ 58,876	C	\$ 29,400
LTIO-540-U2A	N/A	ENPL-8998	\$ 99,779	C	RENPL-8998	\$ 64,736	C	HENPL-8998	\$ 58,639	C	\$ 29,400
O-540-A1A5	YES	ENPL-RT9888	\$ 54,203	C	RENPL-RT9888	\$ 37,363	C	HENPL-RT9888	\$ 33,095	C	\$ 15,800
O-540-A1B5	YES	ENPL-RT9841	\$ 54,393	C	RENPL-RT9841	\$ 37,546	C	HENPL-RT9841	\$ 33,278	C	\$ 15,800
O-540-A1C5	YES	ENPL-RT9866	\$ 54,471	C	RENPL-RT9866	\$ 37,621	C	HENPL-RT9866	\$ 33,353	C	\$ 15,800
O-540-A1D5	YES	ENPL-RT9840	\$ 54,481	C	RENPL-RT9840	\$ 37,630	C	HENPL-RT9840	\$ 33,362	C	\$ 15,800
O-540-A1D5	YES	ENPL-RT9939	\$ 54,637	C	RENPL-RT9939	\$ 37,780	C	HENPL-RT9939	\$ 33,512	C	\$ 15,800
O-540-A4D5	YES	ENPL-RT10123	\$ 55,517	C	RENPL-RT10123	\$ 38,625	C	HENPL-RT10123	\$ 34,357	C	\$ 15,800

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
O-540-B1A5	YES	ENPL-RT9811	\$ 55,965	C	RENPL-RT9811	\$ 37,618	C	HENPL-RT9811	\$ 33,349	C	\$ 16,900
O-540-B2B5	YES	ENPL-RT8686	\$ 56,467	C	RENPL-RT8686	\$ 38,100	C	HENPL-RT8686	\$ 33,832	C	\$ 16,900
O-540-B2B5	YES	ENPL-RT9615	\$ 57,223	C	RENPL-RT9615	\$ 38,826	C	HENPL-RT9615	\$ 34,558	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT10030	\$ 59,668	C	RENPL-RT10030	\$ 41,174	C	HENPL-RT10030	\$ 36,906	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT10157	\$ 59,732	C	RENPL-RT10157	\$ 41,235	C	HENPL-RT10157	\$ 36,967	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT8588	\$ 59,680	C	RENPL-RT8588	\$ 41,186	C	HENPL-RT8588	\$ 36,918	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT9484	\$ 59,847	C	RENPL-RT9484	\$ 41,346	C	HENPL-RT9484	\$ 37,078	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT9953	\$ 59,991	C	RENPL-RT9953	\$ 41,484	C	HENPL-RT9953	\$ 37,216	C	\$ 16,900
O-540-B4B5	YES	ENPL-RT9359	\$ 56,156	C	RENPL-RT9359	\$ 37,801	C	HENPL-RT9359	\$ 33,533	C	\$ 16,900
O-540-B4B5	YES	ENPL-RT9491	\$ 56,974	C	RENPL-RT9491	\$ 38,587	C	HENPL-RT9491	\$ 34,318	C	\$ 16,900
O-540-B4B5	YES	ENPL-RT9594	\$ 57,012	C	RENPL-RT9594	\$ 38,623	C	HENPL-RT9594	\$ 34,355	C	\$ 16,900
O-540-B4B5	YES	ENPL-RT9879	\$ 55,659	C	RENPL-RT9879	\$ 37,323	C	HENPL-RT9879	\$ 33,055	C	\$ 16,900
O-540-B4B5 *	YES	ENPL-RT10358	\$ 56,625	C	RENPL-RT10358	\$ 38,252	C	HENPL-RT10358	\$ 33,984	C	\$ 16,900
O-540-E4A5	YES	ENPL-RT8395	\$ 56,293	C	RENPL-RT8395	\$ 37,933	C	HENPL-RT8395	\$ 33,665	C	\$ 16,900
O-540-E4A5	YES	ENPL-RT8514	\$ 56,194	C	RENPL-RT8514	\$ 37,837	C	HENPL-RT8514	\$ 33,569	C	\$ 16,900
O-540-E4A5	YES	ENPL-RT9444	\$ 57,252	C	RENPL-RT9444	\$ 38,853	C	HENPL-RT9444	\$ 34,585	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10008	\$ 56,353	C	RENPL-RT10008	\$ 37,990	C	HENPL-RT10008	\$ 33,722	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10044	\$ 55,791	C	RENPL-RT10044	\$ 37,450	C	HENPL-RT10044	\$ 33,182	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10075	\$ 55,945	C	RENPL-RT10075	\$ 37,598	C	HENPL-RT10075	\$ 33,330	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10079	\$ 55,968	C	RENPL-RT10079	\$ 37,621	C	HENPL-RT10079	\$ 33,353	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10550	\$ 55,878	C	RENPL-RT10550	\$ 37,535	C	HENPL-RT10550	\$ 33,266	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT8655	\$ 55,945	C	RENPL-RT8655	\$ 37,598	C	HENPL-RT8655	\$ 33,330	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT8890	\$ 56,365	C	RENPL-RT8890	\$ 38,001	C	HENPL-RT8890	\$ 33,733	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT9690	\$ 56,684	C	RENPL-RT9690	\$ 38,308	C	HENPL-RT9690	\$ 34,040	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT9825	\$ 56,348	C	RENPL-RT9825	\$ 37,985	C	HENPL-RT9825	\$ 33,717	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT9961	\$ 56,313	C	RENPL-RT9961	\$ 37,952	C	HENPL-RT9961	\$ 33,683	C	\$ 16,900
O-540-E4B5 *	YES	ENPL-RT9886	\$ 55,979	C	RENPL-RT9886	\$ 37,631	C	HENPL-RT9886	\$ 33,362	C	\$ 16,900
O-540-E4C5	YES	ENPL-RT10132	\$ 55,809	C	RENPL-RT10132	\$ 37,468	C	HENPL-RT10132	\$ 33,200	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT8566	\$ 56,489	C	RENPL-RT8566	\$ 38,121	C	HENPL-RT8566	\$ 33,852	A	\$ 16,900
O-540-E4C5	YES	ENPL-RT9538	\$ 55,373	C	RENPL-RT9538	\$ 37,049	C	HENPL-RT9538	\$ 32,781	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9736	\$ 56,128	C	RENPL-RT9736	\$ 37,774	C	HENPL-RT9736	\$ 33,506	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9885	\$ 55,825	C	RENPL-RT9885	\$ 37,483	C	HENPL-RT9885	\$ 33,215	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9928	\$ 55,821	C	RENPL-RT9928	\$ 37,479	C	HENPL-RT9928	\$ 33,211	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9931	\$ 56,473	C	RENPL-RT9931	\$ 38,106	C	HENPL-RT9931	\$ 33,837	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9974	\$ 56,446	C	RENPL-RT9974	\$ 38,080	C	HENPL-RT9974	\$ 33,811	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9998	\$ 55,867	C	RENPL-RT9998	\$ 37,524	C	HENPL-RT9998	\$ 33,256	B	\$ 16,900
O-540-F1B5	YES	ENPL-RT10140	\$ 57,848	C	RENPL-RT10140	\$ 39,426	C	HENPL-RT10140	\$ 35,157	C	\$ 16,900
O-540-F1B5	YES	ENPL-RT10220	\$ 57,848	C	RENPL-RT10220	\$ 39,730	C	HENPL-RT10220	\$ 35,461	C	\$ 16,900
O-540-F1B5	YES	ENPL-RT10292	\$ 57,847	C	RENPL-RT10292	\$ 39,425	C	HENPL-RT10292	\$ 35,157	C	\$ 16,900
O-540-F1B5	YES	ENPL-RT9793	\$ 57,848	C	RENPL-RT9793	\$ 39,730	C	HENPL-RT9793	\$ 35,461	C	\$ 16,900
O-540-G1A5	YES	ENPL-RT8583	\$ 58,700	C	RENPL-RT8583	\$ 40,244	C	HENPL-RT8583	\$ 35,976	C	\$ 16,900
O-540-H2A5	YES	ENPL-RT8480	\$ 58,699	C	RENPL-RT8480	\$ 40,245	C	HENPL-RT8480	\$ 35,976	C	\$ 16,900
O-540-J1A5D	YES	ENPL-RT7208	\$ 57,029	C	RENPL-RT7208	\$ 38,639	C	HENPL-RT7208	\$ 34,371	C	\$ 16,900
O-540-J3A5	YES	ENPL-RT8843	\$ 54,106	C	RENPL-RT8843	\$ 35,832	C	HENPL-RT8843	\$ 31,564	C	\$ 16,900
O-540-J3A5	YES	ENPL-RT9492	\$ 57,569	C	RENPL-RT9492	\$ 39,159	C	HENPL-RT9492	\$ 34,890	C	\$ 16,900
O-540-J3A5D	YES	ENPL-RT6623	\$ 58,088	C	RENPL-RT6623	\$ 39,657	C	HENPL-RT6623	\$ 35,389	C	\$ 16,900
O-540-J3A5D	YES	ENPL-RT8449	\$ 58,463	C	RENPL-RT8449	\$ 40,017	C	HENPL-RT8449	\$ 35,748	C	\$ 16,900
O-540-J3C5D	YES	ENPL-RT10517	\$ 57,762	C	RENPL-RT10517	\$ 39,344	C	HENPL-RT10517	\$ 35,076	C	\$ 16,900
O-540-J3C5D	YES	ENPL-RT8167	\$ 58,015	C	RENPL-RT8167	\$ 39,586	C	HENPL-RT8167	\$ 35,318	C	\$ 16,900
O-540-L3C5D	YES	ENPL-RT8168	\$ 60,397	C	RENPL-RT8168	\$ 41,874	C	HENPL-RT8168	\$ 37,606	C	\$ 16,900
TIO-540-A2B	N/A	ENPL-10252	\$ 92,012	C	RENPL-10252	\$ 67,496	C	HENPL-10252	\$ 61,399	C	\$ 22,000
TIO-540-A2B	N/A	ENPL-8876	\$ 92,316	C	RENPL-8876	\$ 67,789	C	HENPL-8876	\$ 61,692	C	\$ 22,000
TIO-540-A2B	N/A	ENPL-9408	\$ 91,725	C	RENPL-9408	\$ 67,221	C	HENPL-9408	\$ 61,124	C	\$ 22,000
TIO-540-A2C	N/A	ENPL-8269	\$ 92,282	C	RENPL-8269	\$ 67,667	C	HENPL-8269	\$ 61,569	C	\$ 22,000
TIO-540-A2C	N/A	ENPL-8352	\$ 92,130	C	RENPL-8352	\$ 68,732	C	HENPL-8352	\$ 62,635	C	\$ 22,000

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE											
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
TIO-540-A2C	N/A	ENPL-9410	\$ 92,141	C	RENPL-9410	\$ 68,153	C	HENPL-9410	\$ 62,055	C	\$ 22,000
TIO-540-A2C	N/A	ENPL-9411	\$ 91,383	C	RENPL-9411	\$ 66,893	C	HENPL-9411	\$ 60,795	C	\$ 22,000
TIO-540-A2C	N/A	ENPL-9959	\$ 92,296	C	RENPL-9959	\$ 67,769	C	HENPL-9959	\$ 61,672	C	\$ 22,000
TIO-540-AA1AD	N/A	ENPL-8459	\$ 104,982	D	RENPL-8459	\$ 79,955	D	HENPL-8459	\$ 73,857	D	\$ 22,000
TIO-540-AA1AD	N/A	ENPL-8692	\$ 105,103	D	RENPL-8692	\$ 80,071	D	HENPL-8692	\$ 73,973	D	\$ 22,000
TIO-540-AA1AD	N/A	ENPL-8824	\$ 105,924	D	RENPL-8824	\$ 80,860	D	HENPL-8824	\$ 74,762	D	\$ 22,000
TIO-540-AB1AD	N/A	ENPL-7459	\$ 91,818	D	RENPL-7459	\$ 67,310	D	HENPL-7459	\$ 61,213	D	\$ 22,000
TIO-540-AB1AD	N/A	ENPL-8749	\$ 91,681	D	RENPL-8749	\$ 67,179	D	HENPL-8749	\$ 61,081	D	\$ 22,000
TIO-540-AB1BD	N/A	ENPL-8952	\$ 87,214	D	RENPL-8952	\$ 62,888	D	HENPL-8952	\$ 56,791	D	\$ 22,000
TIO-540-AE2A	N/A	ENPL-10033	\$ 122,196	D	RENPL-10033	\$ 96,489	D	HENPL-10033	\$ 90,392	D	\$ 22,000
TIO-540-AE2A	N/A	ENPL-10034	\$ 122,196	D	RENPL-10034	\$ 96,489	D	HENPL-10034	\$ 90,392	D	\$ 22,000
TIO-540-AE2A	N/A	ENPL-10037	\$ 120,941	D	RENPL-10037	\$ 95,284	D	HENPL-10037	\$ 89,186	D	\$ 22,000
TIO-540-AF1B	N/A	ENPL-9906	\$ 93,757	D	RENPL-9906	\$ 69,173	D	HENPL-9906	\$ 63,076	D	\$ 22,000
TIO-540-AG1A	N/A	ENPL-9642	\$ 85,990	D	RENPL-9642	\$ 61,123	D	HENPL-9642	\$ 55,025	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-10125	\$ 105,636	D	RENPL-10125	\$ 80,583	D	HENPL-10125	\$ 74,485	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-9660	\$ 105,691	D	RENPL-9660	\$ 80,636	D	HENPL-9660	\$ 74,539	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-9813	\$ 105,701	D	RENPL-9813	\$ 80,645	D	HENPL-9813	\$ 74,548	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-10545	\$ 105,636	D	RENPL-10545	\$ 80,582	D	HENPL-10545	\$ 74,485	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-10490	\$ 103,280	D	RENPL-10490	\$ 78,320	D	HENPL-10490	\$ 72,222	D	\$ 22,000
TIO-540-AJ1A	YES	ENPL-RT10249	\$ 111,406	D	RENPL-RT10249	\$ 86,126	D	HENPL-RT10249	\$ 80,028	D	\$ 22,000
TIO-540-AJ1A	YES	ENPL-RT10269	\$ 111,514	D	RENPL-RT10269	\$ 86,229	D	HENPL-RT10269	\$ 80,132	D	\$ 22,000
TIO-540-AJ1A	YES	ENPL-9734	\$ 111,337	D	RENPL-9734	\$ 86,059	D	HENPL-9734	\$ 79,961	D	\$ 22,000
TIO-540-AK1A	N/A	ENPL-10385	\$ 90,707	D	RENPL-10385	\$ 66,243	D	HENPL-10385	\$ 60,145	D	\$ 22,000
TIO-540-AK1A	N/A	ENPL-10048	\$ 90,613	D	RENPL-10048	\$ 66,153	D	HENPL-10048	\$ 60,056	D	\$ 22,000
TIO-540-AK1A	N/A	ENPL-10439	\$ 90,909	D	RENPL-10439	\$ 66,376	D	HENPL-10439	\$ 60,278	D	\$ 22,000
TIO-540-C1A	N/A	ENPL-6620	\$ 97,448	D	RENPL-6620	\$ 72,719	D	HENPL-6620	\$ 66,621	D	\$ 22,000
TIO-540-C1A	N/A	ENPL-6621	\$ 97,448	D	RENPL-6621	\$ 72,719	D	HENPL-6621	\$ 66,621	D	\$ 22,000
TIO-540-C1A	N/A	ENPL-8662	\$ 97,464	D	RENPL-8662	\$ 72,733	D	HENPL-8662	\$ 66,636	D	\$ 22,000
TIO-540-F2BD	N/A	ENPL-8198	\$ 93,110	C	RENPL-8198	\$ 68,551	C	HENPL-8198	\$ 62,454	C	\$ 22,000
TIO-540-J2B	N/A	ENPL-10296	\$ 90,834	C	RENPL-10296	\$ 66,418	C	HENPL-10296	\$ 60,320	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-10384	\$ 91,765	C	RENPL-10384	\$ 67,312	C	HENPL-10384	\$ 61,214	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-10417	\$ 90,834	C	RENPL-10417	\$ 66,418	C	HENPL-10417	\$ 60,320	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-8120	\$ 90,834	C	RENPL-8120	\$ 66,418	C	HENPL-8120	\$ 60,320	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-8945	\$ 90,834	C	RENPL-8945	\$ 66,418	C	HENPL-8945	\$ 60,320	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-9401	\$ 90,833	C	RENPL-9401	\$ 66,417	C	HENPL-9401	\$ 60,319	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-9606	\$ 91,905	C	RENPL-9606	\$ 67,447	C	HENPL-9606	\$ 61,349	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-10301	\$ 91,708	C	RENPL-10301	\$ 67,257	C	HENPL-10301	\$ 61,159	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-10554	\$ 91,348	C	RENPL-10554	\$ 66,911	C	HENPL-10554	\$ 60,814	B	\$ 22,000
TIO-540-J2BD	N/A	ENPL-8147	\$ 92,824	C	RENPL-8147	\$ 67,671	C	HENPL-8147	\$ 61,574	A	\$ 22,000
TIO-540-J2BD	N/A	ENPL-9789	\$ 92,579	C	RENPL-9789	\$ 67,436	C	HENPL-9789	\$ 61,339	A	\$ 22,000
TIO-540-S1AD	N/A	ENPL-10279	\$ 93,416	D	RENPL-10279	\$ 69,374	D	HENPL-10279	\$ 63,277	D	\$ 22,000
TIO-540-S1AD	N/A	ENPL-8179	\$ 94,179	D	RENPL-8179	\$ 70,114	D	HENPL-8179	\$ 64,016	D	\$ 22,000
TIO-540-S1AD	N/A	ENPL-9426	\$ 93,415	D	RENPL-9426	\$ 69,374	D	HENPL-9426	\$ 63,276	D	\$ 22,000
TIO-540-U2A	N/A	ENPL-8868	\$ 97,285	C	RENPL-8868	\$ 62,340	C	HENPL-8868	\$ 56,243	C	\$ 29,400
TIO-540-U2A	N/A	ENPL-8894	\$ 99,015	C	RENPL-8894	\$ 64,002	C	HENPL-8894	\$ 57,905	C	\$ 29,400
TIO-540-U2A	N/A	ENPL-9663	\$ 99,015	C	RENPL-9663	\$ 64,002	C	HENPL-9663	\$ 57,905	C	\$ 29,400
TIO-540-U2A	N/A	ENPL-9872	\$ 99,322	C	RENPL-9872	\$ 64,297	C	HENPL-9872	\$ 58,200	C	\$ 29,400
TIO-540-W2A	N/A	ENPL-9434	\$ 122,160	D	RENPL-9434	\$ 86,234	D	HENPL-9434	\$ 80,136	D	\$ 29,400
AEIO-580-B1A	YES	ENPL-RT10568	\$ 86,458	D	RENPL-RT10568	\$ 63,458	D	HENPL-RT10568	\$ 57,361	D	\$ 28,200
AEIO-580-B1A	YES	ENPL-RT10427	\$ 86,023	D	RENPL-RT10427	\$ 63,040	D	HENPL-RT10427	\$ 56,943	D	\$ 28,200
AEIO-580-B1A	YES	ENPL-RT10617	\$ 87,077	D	RENPL-RT10617	\$ 64,053	D	HENPL-RT10617	\$ 57,956	D	\$ 28,200
IO-720-A1B	N/A	ENPL-7356	\$ 128,352	D	RENPL-7356	\$ 81,073	D	HENPL-7356	\$ 71,927	D	\$ 40,300
IO-720-A1B	N/A	ENPL-7371	\$ 131,764	D	RENPL-7371	\$ 84,350	D	HENPL-7371	\$ 75,204	D	\$ 40,300
IO-720-A1B	N/A	ENPL-7491	\$ 130,218	D	RENPL-7491	\$ 82,866	D	HENPL-7491	\$ 73,719	D	\$ 40,300
IO-720-A1B	N/A	ENPL-8546	\$ 130,389	D	RENPL-8546	\$ 83,029	D	HENPL-8546	\$ 73,883	D	\$ 40,300

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST
 Effective July 5, 2011
 (Prices in U.S. Dollars)

"MSRP" REPRESENTS MANUFACTURES SUGGESTED RETAIL EXCHANGE PRICE
PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES

ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
IO-720-B1B	N/A	ENPL-9578	\$ 126,378	D	RENPL-9578	\$ 79,177	D	HENPL-9578	\$ 70,031	D	\$ 40,300
IO-720-D1B	N/A	ENPL-7488	\$ 132,542	D	RENPL-7488	\$ 85,098	D	HENPL-7488	\$ 75,951	D	\$ 40,300
IO-720-D1C	N/A	ENPL-7218	\$ 129,815	D	RENPL-7218	\$ 82,478	D	HENPL-7218	\$ 73,332	D	\$ 40,300

DC = Delivery/Return/Cancellation Code
 * = No Starter ** = New Cam
 *** = New Rods **** = Top End Chrome
 Domestic Freight - 4 cyl \$139
 Domestic Freight - 6 cyl \$199
 New Outright price equals (new exchange price X 1.2).